MESSAGES

CLAIMS



General & Workshop Detail	ils Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
General Details			Workshop De	tails		
Involving	TPVD UNKNOWN UNKNOWN (SLV7716P)	Total Rebate Am	nount 44452	<u>)</u>	
Date of Loss	23 January 2021		Nett Loss Amou	nt \$26,548	3.00	
Time of Loss	15.30		Assigned Works	hop LKK AU	TO CONSULTANTS	FPTE LTD (TP)
Loss Description	SHB6361M (INSD) HIT REAR OF (TP)	SLV7716P	Days of work completion *	20		
Comment						

MESSAGES

CLAIMS



General & Workshop	Details Vehic	le & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & L	abour .	Miscellaneous	Summa	ary
Vehicle & Driver De	tails								
Vehicle Registration#	SLV7716P			Purchase Date		dd/mm/	уууу		
Registration State	SINGAPOF	RE		Registration Date	*	15/01/2	018		
Mileage	105007			Age of Vehicle		3			
CATEGORY	POLICY INFORMATION	ASSESSMENT INF	ORMATION	Driver Details					
Manufacturing		2017		CATEGORY	FN: INF	OL FORMATION		T SURVEY DRMATION	
Year				Driver Name	ТВ	C			
Make	TPVD UNKNOWN	HONDA		Date of Birth			dd	/mm/yyyy	
				Bate of Biltin			uu	, , , , , , , , , , , , , , , , , , , ,	ш

Model CATEGORY	HOLKIYOWN INFORMATION	CIVIC 1.6 VTI CVT	CATEGORY Age	FNOL (INFORMATION	POST SURVEY INFORMATION
Туре		•	Occupation	Unknown	
Type of Paint			Education Qualification	Other	•
Chassis No		MRHFC5650HT000701	Driving Experience	0	
Engine No		R16B22001116	Driver License #		
Engine Capacity		1597	License Type		•
Sum Insured		0	License Issue Date		dd/mm/yyyy 🛗
Market Value		71000	License Expiration Date		dd/mm/yyyy 🏥

CATEGORY Address	FNOL LYFORMATION SCF, Singapore	POST SURVEY
Address type	Personal Correspondence	•
Gender	Unknown	•
Marital status	Unknown	•
Identification #	ТВС	

MESSAGES

CLAIMS



General & Workshop Det	tails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Lab	our	Miscellaneous	Summary
Detailed Assessment			Condition of Veh	nicle at tir	ne of s	survey	
Inspection Date *	27/01/2021		General condition		Good		•
Total Loss	Yes No		Steering (Serviceab	ole)	Yes	No	
Towing Charges	0		Footbrake (Services	able)	Yes	No	
Voluntary Excess Compulsory Excess	0		Handbrake (Serviceable)		Yes	No	
Young/Inexperienced/ Unnamed Driver	0		Engine Modification	n	Yes	No	
Excess			Pre-accident condit	tion	Good		•

Other Excess		Tyre Condition	
Age of Tyres		Spare wheel	
Front Tyre Size	215/55R16	Rear Tyre Size	215/55R16
Front left side	YOKOHAMA8mm	Rear left side	YOKOHAMA8mm
Front right side	YOKOHAMA8mm	Rear right side	YOKOHAMA8mm

MESSAGES

CLAIMS



General & Workshop Details	s Vehicle & Driver Details	Vehicle Conditi	ion Taxes & Ratio	Parts & Labour	Miscellaneous -	Summary
Tax Eligibility & Additiona	al Deduction for Parts					
Depr./Bttr%			Salvage%			
Discount%	20		Settlement%	100		
Paint Labour/Material Ra	itio					
Paint Labour Ratio	20		Paint Material R	atio 80		
Cash Loss		Yes N	No			
Part Supplied by AXA		Yes N	No			

General & Workshop Details Vehicle & Driver Details

MESSAGES

CLAIMS

Vehicle Condition Taxes & Ratio

Assessment Details

									<u> </u>						
Parts															
Add	Approve	Deny	Submit A	I											
	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
	Ø	0	1		REAR BUMPER FASCIA	Buckled	0	617.2	No		20			493.76	Reviewing
	Ø	0	1		RH REAR BUMPER REFLECTOR	Serviceable	0	0	No		20			0	Deny
	D	0	1		REAR BUMPER REVERSE SENSORS (4PCS)	Shorted	0	189.2	No		20			151.36	Reviewing
	D	0	1		REAR BUMPER SIDE RETAINER O/S	Damaged	0	14.5	No		20			11.6	Reviewing
	ø	0	1		REAR BUMPER SIDE RETAINER N/S	Serviceable	0	0	No		20			0	Deny

Parts & Labour Miscellaneous

Summary

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
	Ø	0	2		REAR BUMPER BRACKETS	Repair	0	0	No		20			0	Deny
	Ď	0	1		REAR BUMPER LOWER GARNISH	Serviceable	0	0	No		20			0	Deny
	P	0	1		RH TAIL LAMP ASSY	Cracked	0	264.1	No		20			211.28	Reviewing
	P	0	1		REAR END PANEL	Repair	0	0	No		20			0	Deny
	Ď	0	1		REAR END PANEL TOP GARNISH	Serviceable	0	0	No		20			0	Deny
	P	0	1		RH REAR FENDER	Bent	0	711.6	No		20			569.28	Reviewing
	Ď	0	1		RH REAR FENDER AIR VENT	Dented	0	56.6	No		20			45.28	Reviewing
	Ď	0	1		RH REAR FENDER INNER SHIELD	Serviceable	0	0	No		20			0	Deny
	Ď	0	1		RH REAR FENDER INNER TRIM	Serviceable	0	0	No		20			0	Deny
	Ď	0	1		REAR WINDSCREEN MOULDING	Necessary	0	85.5	No		20			68.4	Reviewing
Labour															

Add	Approve	Deny	Submit All							
	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
	Ø	0		CHECK ELECTRICAL WIRINGS	0	20	0	0	Reviewing	
	Ø	0		REPAIR ACCIDENT DAMAGES AND REPLACE ABOVE PARTS	0	600	0	0	Reviewing	
	Ø	0		SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS	0	600	0	0	Reviewing	
	Ø	0		RENEW REVERSE SENSOR	0	50	0	0	Reviewing	
	Ø	0		REMOVE INTERIOR UPHOLSTERY TO FACILITATE REPAIR	0	100	0	0	Reviewing	
	Ø	0		REMOVE AND REFIT REAR WINDSCREEN	0	120	0	0	Reviewing	
	Ø	0		RUST PROOFING ON ACCIDENT AFFECTED PORTIONS	0	30	0	0	Reviewing	

MESSAGES

CLAIMS



I & Worksho	p Details	Vehicle & Driver D	Details Vehic	le Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary .
Approve	Deny	Submit All						
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE	
Ď	0	DAYS OF REPAIR : 5 DAYS	Reviewing		0		ш	
Ø	0	1 SET REAR BUMPER CLIPS	Reviewing		45	NECESSARY	ŵ	
Ø.	0	REAR WINDSCREEN SEALANT	Reviewing		40	NECESSARY	ш	
	Approve EDIT	EDIT SR NO	Approve Deny Submit All EDIT SR NAME DAYS OF REPAIR: 5 DAYS 1 SET REAR BUMPER CLIPS REAR WINDSCREEN	Approve Deny Submit All EDIT SR NAME ACTION DAYS OF REPAIR: 5 DAYS O 1 SET REAR BUMPER CLIPS Reviewing REAR WINDSCREEN Reviewing	Approve Deny Submit All EDIT SR NAME ACTION ESTIMATED AMOUNT DAYS OF REPAIR: 5 DAYS DAYS 1 SET REAR BUMPER CLIPS Reviewing CLIPS Reviewing Reviewing Reviewing Reviewing	Approve Deny Submit All EDIT SR NAME ACTION ESTIMATED AMOUNT DAYS OF REPAIR: 5 DAYS DAYS O SET REAR BUMPER CLIPS Reviewing O REAR WINDSCREEN Reviewing 40	Approve Deny Submit All EDIT SR NAME ACTION ESTIMATED ADJUSTED COMMENT AMOUNT AMOUNT OF REPAIR: 5 DAYS O 1 SET REAR BUMPER CLIPS Reviewing 0 REAR WINDSCREEN Reviewing 40 NECESSARY	Approve Deny Submit All EDIT SR NAME ACTION ESTIMATED AMOUNT COMMENT REMOVE O DAYS OF REPAIR: 5 DAYS DAYS Reviewing O 1 SET REAR BUMPER CLIPS Reviewing 45 NECESSARY REAR WINDSCREEN Reviewing 40 NECESSARY

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00	0		Adjusted Claim Amount	\$3,155.	96	
CATEGORY		ESTIMATE	ADJUSTED				
Spare Parts		\$0.00	\$1,550.96				
Labour		\$0.00	\$1,520.00				
Miscellaneous		\$0.00	\$85.00				

Submit for Review

MESSAGES

CLAIMS



General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Lab	our <u>.</u>	Miscellaneous	Summary .	
Add	Approve	Deny	Submit All							
	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOV	/E	
	<i>i</i>	0	FINAL LUMP SUM	Reviewing		2500		ŵ		

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$2,500.0	ı	
CATEGORY		ESTIMATE	ADJUSTED				
Miscellaneous		\$0.00	\$2,500.00				

Submit for Review