



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11495/KAMSANI BIN JANTAN Reg No/Reg Date SMQ3930C / 14/11/201 Date In/Mileage 26/01/2021/ 0 Chassis No KNAF5416MK5051851 Engine No G4FGKH748537 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	26/01/2021/ 12:27	QUK	282 / Kevin Leong	28077

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER PANEL, SUPPORT PANEL & AFFECTED AREA				400 1200.00
E PNT98000 PAINT WORK ON FRT BUMPER PANEL				350 700.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR				120.00 X
M SUNDRY TO TOP UP AIRCON GAS				80.00 X
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				120.00
M SUNDRY TO SUPPLY FRONT NUMBER PLATE WITH FRAME				50.00
M SUNDRY SUNDRIES				20 50.00
M LAMP ASSY-HEAD, RH CUT ? X NM	1.00	2210.00	20.00	1768.00
M CARRIER ASSY-FRONT END MODULE ? X NM	1.00	675.00	20.00	540.00
M BEAM COMPLETE-FR BUMPER ? X NM	1.00	497.00	20.00	397.60
M COVER-FR BUMPER BR ?	1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER CUT ? X NM	1.00	485.00	20.00	388.00
M COVER-FR BUMPER FOG LAMP, RH ? X NM	1.00	15.00	20.00	12.00
M LAMP ASSY-FRONT FOG, RH ? X NM	1.00	303.00	20.00	242.40
M MOULDING-FRONT BUMPER, RH CUT (fy lq)	1.00	216.00	20.00	172.80
M LAMP ASSY-SIDE REPEATER, RH CUT	1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER, RH ? X NM	1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY ? OR	1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR ? X NM	1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE MTG X NM	1.00	22.00	20.00	17.60
M GRILLE ASSY-RADIATOR CUT ?	1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE ? BR	1.00	38.00	20.00	30.40
M WIRING ASSY-BUMPER EXTENSION ? X NM	1.00	207.00	20.00	165.60

Confirm & accepted by

P/P
My BR SH
3 days

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name	LCV11495/KAMSANI BIN JANTAN
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date	SMQ3930C / 14/11/201
78 SHENTON WAY #09-16	Date In/Mileage	26/01/2021/ 0
AIG BUILDING	Chassis No	KNAF5416MK5051851
SINGAPORE 079120	Engine No	G4FGKH748537
Contact No 64191000	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

					WIP No			
Account No	Terms	Date/Time Printed	CSE	Operator				
LAX00000	Credit	26/01/2021/ 12:27	QUK	282 / Kevin Leong	28077			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	ULTRASONIC SENSOR ASSY-P.A.S	4	X NN		1.00	163.00	20.00	130.40
M	ULTRASONIC SENSOR ASSY-P.A.S	1	X NN		1.00	163.00	20.00	130.40

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by

7446.80

	Nett	7,398.00
7% GST on	7398.00	517.86
Total Payable		7,915.86

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.