

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 24 Jan 2021

ASSESSMENT FOR REPAIR: YAMAHA CZD300A / XMAX300 - FBR898H

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$140.00
1 pc	Right front fork	\$820.00
1 pc	Left front fork	\$820.00
1 pc	Front wheel shaft	\$95.00
1 pc	Front brake disk	\$275.00
1 pc	Steering stem	\$255.00
2 pcs	Steering stem bearings @ \$45.00	\$90.00
1 pc	Centre body inner cover	\$195.00
1 pc	Black front upper cover	\$145.00
1 pc	Black front lower cover	\$135.00
1 pc	Right brake lever	\$65.00
1 pc	Left brake lever	\$65.00
1 pc	Left balancer	\$45.00
1 pc	Handle bar	\$185.00
1 pc	Left fairing	\$145.00
1 pc	Right fairing	\$145.00
1 pc	Left view mirror	\$125.00
1 pc	Right view mirror	\$125.00
2 pcs	Yamaha amblem @ \$45.00	\$90.00
1 pc	Lower left cover	\$135.00
1 pc	Lower right cover	\$135.00
1 pc	Belly pan	\$155.00
1 pc	Front windshield assy	\$145.00
1 pc	Right box holder assy	\$195.00
1 pc	Radiator assy	\$475.00
1 pc	Right lower cover	\$145.00
1 pc	Right floor step	\$135.00
1 pc	Left floor step	\$135.00
1 pc	Center inner cover	\$185.00
		<hr/>
		\$5,800.00
	Less discount 10%	\$580.00
		<hr/>
		\$5,220.00
	<u>Special nett items</u>	
1 pc	Front sport rim	\$650.00
1)	Towing charges	\$120.00

2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$700.00
3)	To replace and balance front wheel rim	\$150.00
4)	To knock, straighten chassis & body balancing	\$380.00
5)	Spray painting	\$350.00
6)	Reset meter	\$120.00
7)	To replace and refit and align front forks	\$180.00
Total Estimate		<u><u>\$7,690.00</u></u>

Note: The above estimate is subjected to the prevailing GST of 7%

For Bike Production Pte Ltd