

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 27 Jan 2021

Preliminary Advice

Vehicle No	: SLC532Z	Accident Date	: 22/01/2021
Make	: MERCEDES-BENZ C200	Policy No.	: 999995580
Assignment Date	: 26/01/2021	Excess	: S\$0.00
Date of Inspection	: 27/01/2021	Est. Duration of Repair	: 6
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,172.65
Revised Amount	:S\$	13,136.45
Check Items (Estimated)	:S\$	3,236.20
Total	:S\$	16,372.65

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	109,000.00
COE / PARF Rebate	:S\$	61,344.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,656.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :