



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tflauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2021

ESTIMATE

NO : QUOT202101-000059(00)

DATE : 26/01/2021

POLICY NO : 999995580

VEH REG NO : SLC532Z

MAKE/MODEL : MERCEDES BENZ C200
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050422R159732

ENGINE NO : 27492030577080

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLC532Z

Description	Quantity	Unit Price	Amount		
			S\$	S\$	
PARTS					
1 Bonnet	1	<i>Bu</i> 1,290.00	1,290.00		✓
2 Bonnet hinges - RH / LH	1	135.00	135.00		?
3 Bonnet Insulator clips	10	5.50	55.00		?
4 Support panel	1	480.00	<i>Bu</i> 480.00		✓
5 Front grille	1	120.00	<i>CM</i> 120.00		✓
6 Front grille support	1	195.00	<i>NI</i> 195.00		✓
7 Front grille beam	1	205.00	205.00		?
8 Front grille beam chrome	<i>A 2</i>	58.00	<i>NI</i> 232.00		✓
9 Front grille centre logo	1	118.00	<i>NI</i> 118.00		✓
10 Front grille center logo base	1	62.00	62.00		?
11 Headlamp assy - RH / LH	2	2,750.00	5,500.00		✓
12 Front bumper	1	980.00	<i>CM</i> 980.00		✓
13 Front bumper reinforcement	1	325.00	325.00		?
14 Front bumper sponge	1	155.00	155.00		?
15 Front bumper side retainer - RH / LH	2	38.00	<i>DIY</i> 76.00		✓
16 Front bumper inside part - center	1	78.00	78.00		?
17 Front bumper inside parts - RH / LH	2	72.00	144.00		?
18 Front bumper lower grille	1	98.00	98.00		?
19 Front bumper lower chrome	1	135.00	135.00		?
20 Front bumper fog lamp cover	1	58.00	<i>NI</i> 58.00		✓
21 Front bumper sensor	4	138.00	552.00		?
22 Front bumper sensor seals	6	8.00	48.00		?
23 Front bumper clips	15	5.50	<i>NI</i> 82.50		✓
24 Front fender - RH / LH	2	<i>Bu</i> 620.00	1,240.00		✓
25 Air-con condenser	1	950.00	950.00		?
26 Front number plate garnish	1	98.00	<i>NI</i> 98.00		✓
			13,411.50		
			Add 10%	1,341.15	
				14,752.65	
SPECIAL NET					
27 Front number plate	1	40.00	<i>NI</i> 40.00		✓
				40.00	
LABOUR					
28 To remove and refit air-con condenser and refill air-con gas	1	150.00	150.00		<i>100%</i>



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2021

ESTIMATE

NO : QUOT202101-000059(00)

DATE : 26/01/2021

POLICY NO : 999995580

VEH REG NO : SLC532Z

MAKE/MODEL : MERCEDES BENZ C200
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050422R159732

ENGINE NO : 27492030577080

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLC532Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
29 To remove and refit front bumper sensor	1	100.00	100.00
30 To check and rectify wiring system	1	80.00	80.00
31 To panel beat and straighten, both side front fender inner panel, front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00
32 To putty and spray paint on affected areas	1	1,500.00	1,500.00
33 To reset and reprogramme headlamp fault code	1	350.00	350.00
			3,380.00
		TOTAL	S\$ 18,172.65
		ADD GST @ 7%	1,272.09
		GRAND TOTAL	S\$ 19,444.74

601
201
6001
8001
?

SINGAPORE DOLLAR NINETEEN THOUSAND FOUR HUNDRED FORTY-FOUR AND CENTS SEVENTY-FOUR ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 23/01/2021 01:57 (SGT)
Date of Accident 22/01/2021 08:30 (SGT)
Exact Location of Accident Bedok, Singapore
Additional Location Information Along ECP toward city, before Bedok South Ave 1 exit
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLC532Z

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
Company Reg No 1XXXXX778Z
Email Address faizal.mohamed@daimler.com
Mobile Phone No (Phone) +65-81268670
Alternative Phone No (Office) +65-81268670

VEHICLE PARTICULARS

Manufacturer Mercedes
Model C200
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company AIG
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number 999995580
Cover Note Number -

DRIVER

Name of Driver KOH TIONG KHENG
NRIC No SXXXX031F
Date Of Birth 07/11/1970
Occupation Indoor

Date Of Driving Pass 06/11/2003
 Driving experience 17 YEARS AND 2 MONTHS
 Gender Male
 Mobile Number (Phone) +65-97116558
 Alt. Phone Number -
 Email Address ronktt@gmail.com
 Address The Gale, 72 Flora Road
 Address complement 06-27
 Postcode 506915
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Hirer
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 3
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other material or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name MR.TAN - CHINESE
 Gender Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

I was driving along ECP towards city, on the extreme right lane when suddenly vehicle B collided against vehicle C. I try to brake but was unable to stop on time and knock against vehicle B. My front portion was damaged and no injury involved.

ATTACHMENT(S)

Are accident photos available for attachment? No
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJP3947X
 Vehicle Manufacturer Honda
 Vehicle Model Fit
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver REUBEN GOH

ETCH PLAN


A-SLCS32Z

B-SJP3947X

C-SMS5553J

Beode
SOUTH
RVE 1

CITY
↑
ECP



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

A large rectangular area with horizontal lines, intended for writing a description of the accident circumstances.

DECLARATION
I declare the foregoing particulars are true in every respect.

ACCIDENT STATEMENT (2000 characters)

I was driving along ecp towards city, on the extreme right lane when suddenly vehicle B collided against vehicle C. I try to brake but was unable to stop on time and knock against vehicle b. My front portion was damaged and no injury involved.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SHARIL BIN SATAR

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

22 January 2021 at 4:09 PM

Date/Time:

22 January 2021 at 4:09 PM