



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2021

ESTIMATE

NO : QUOT202101-000059(00)

DATE : 26/01/2021

POLICY NO : 999995580

VEH REG NO : SLC532Z

MAKE/MODEL : MERCEDES BENZ C200
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050422R159732

ENGINE NO : 27492030577080

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLC532Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1 Bu	1,290.00	1,290.00 ✓
2 Bonnet hinges - RH / LH	1	135.00	135.00 ?
3 Bonnet Insulator clips	10	5.50	55.00 ?
4 Support panel	1	480.00 Bu	480.00 ✓
5 Front grille	1	120.00 CM	120.00 ✓
6 Front grille support	1	195.00 N	195.00 ✓
7 Front grille beam	1	205.00	205.00 ?
8 Front grille beam chrome	4 2	58.00 N	232.00 ✓
9 Front grille centre logo	1	118.00 N	118.00 ✓
10 Front grille center logo base	1	62.00	62.00 ?
11 Headlamp assy -- RH / LH	2	2,750.00 N	5,500.00 ✓
12 Front bumper	1	980.00 CM	980.00 ✓
13 Front bumper reinforcement	1	325.00	325.00 ?
14 Front bumper sponge	1	155.00	155.00 ?
15 Front bumper side retainer - RH / LH	2	38.00 D	76.00 ✓
16 Front bumper inside part - center	1	78.00	78.00 ?
17 Front bumper inside parts - RH / LH	2	72.00	144.00 ?
18 Front bumper lower grille	1	98.00	98.00 ?
19 Front bumper lower chrome	1	135.00	135.00 ?
20 Front bumper fog lamp cover	1	58.00 N	58.00 ✓
21 Front bumper sensor	4	138.00	552.00 ?
22 Front bumper sensor seals	6	8.00	48.00 ?
23 Front bumper clips	15	5.50 N	82.50 ✓
24 Front fender - RH / LH	2 Bu	620.00	1,240.00 ✓
25 Air-con condenser	1	950.00	950.00 ?
26 Front number plate garnish	1	98.00 N	98.00 ✓
			13,411.50
		Add 10%	1,341.15
			14,752.65
SPECIAL NET			
27 Front number plate	1	40.00 N	40.00 ✓
			40.00
LABOUR			
28 To remove and refit air-con condenser and refill air-con gas	1	150.00	150.00 100%



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2021

ESTIMATE

NO : QUOT202101-000059(00)

DATE : 26/01/2021

POLICY NO : 999995580

VEH REG NO : SLC532Z

MAKE/MODEL : MERCEDES BENZ C200
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050422R159732

ENGINE NO : 27492030577080

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLC532Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
29 To remove and refit front bumper sensor	1	100.00	100.00
30 To check and rectify wiring system	1	80.00	80.00
31 To panel beat and straighten, both side front fender inner panel, front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00
32 To putty and spray paint on affected areas	1	1,500.00	1,500.00
33 To reset and reprogramme headlamp fault code	1	350.00	350.00
			3,380.00
		TOTAL	S\$ 18,172.65
		ADD GST @ 7%	1,272.09
		GRAND TOTAL	S\$ 19,444.74

SINGAPORE DOLLAR NINETEEN THOUSAND FOUR HUNDRED FORTY-FOUR AND CENTS SEVENTY-FOUR ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE