

REF: AIG 21001245/Kt

REC. BY:

## ASSIGNMENT

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

06

days

Res.:

Yes or No

Lum Sum:

1-B.1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 5328

Yr Regn:

04, 16

Type: ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A)

Make:

Mer C200

c.c

1991

Colour

M.D. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

88637

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2050422R159732

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/50 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

22/1/21

D.O.I.

27/1/2021

Survey held at

Des. of Damages: ☒ Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/3

R15,592.70

Part by part \$15692.70, 6 days  
cred: 3791.70 (19%)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trlp:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                                 |  |
|---------------------------------|--|
| Date of Submission              | 23/01/2021 01:57 (SGT)                               |
| Date of Accident                | 22/01/2021 08:30 (SGT)                               |
| Exact Location of Accident      | Bedok, Singapore                                     |
| Additional Location Information | Along ECP toward city, before Bedok South Ave 1 exit |
| Country/State of Loss           | Singapore  |

### DETAILS OF OWN VEHICLE

|                             |         |
|-----------------------------|---------|
| Vehicle Registration Number | SLC532Z |
|-----------------------------|---------|

#### INSURED/POLICYHOLDER

|                          |   |
|--------------------------|---|
| Is company?              | Yes   |
| Name Of Registered Owner | DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD |
| Company Reg No           | 1XXXXX778Z                                  |
| Email Address            | faizal.mohamed@daimler.com                  |
| Mobile Phone No          | (Phone) +65-81268670                        |
| Alternative Phone No     | (Office) +65-81268670                       |

#### VEHICLE PARTICULARS

|  |              |
|--|--------------|
| Manufacturer   | Mercedes     |
| Model  | C200         |
| Variant  | -            |
| Exact purpose for which vehicle was being used at time of accident           | Private hire |
| Are you claiming under your own insurance policy for repair to your vehicle? | Yes          |
| Vehicle Category   | Private car  |

#### INSURANCE COMPANY

|                           |               |
|---------------------------|---------------|
| Name of Insurance Company | AIG           |
| Type of Coverage          | Comprehensive |
| Fleet Policy              | Yes           |
| Policy Number             | 999995580     |
| Cover Note Number         | -             |

#### DRIVER

|                |                 |
|----------------|-----------------|
| Name of Driver | KOH TIONG KHENG |
| NRIC No        | SXXXX031F       |
| Date Of Birth  | 07/11/1970      |
| Occupation     | Indoor          |

|   |                      |
|---|----------------------|
| NRIC No                                 | SXXXX857I            |
| Contact Number                          | (Phone) +65-97232629 |
| Address                                 | -                    |
| Address complement                      | -                    |
| Postcode                                | -                    |
| Insurance Company Name                  | -                    |
| Nature Of Damage                        | -                    |
| Details of property damaged in accident | -                    |
| No. Of Passenger (Including Driver)     | 1                    |

#### DETAILS OF OTHER VEHICLE PROPERTY 2

|   |                      |
|---|----------------------|
| Vehicle Registration Number             | SMS5553J             |
| Vehicle Manufacturer                    | LandRover            |
| Vehicle Model                           | Evoque               |
| Vehicle Variant                         | -                    |
| Vehicle Colour                          | -                    |
| Vehicle Category                        | Private car          |
| Name of Driver                          | MARGARET SAMIN       |
| NRIC No                                 | SXXXX531G            |
| Contact Number                          | (Phone) +65-86138817 |
| Address                                 | -                    |
| Address complement                      | -                    |
| Postcode                                | -                    |
| Insurance Company Name                  | -                    |
| Nature Of Damage                        | -                    |
| Details of property damaged in accident | -                    |
| No. Of Passenger (Including Driver)     | 1                    |

SKETCH PLAN #2





**ACCIDENT STATEMENT (2000 characters)**

I was driving along ecp towards city, on the extreme right lane when suddenly vehicle B collided against vehicle C. I try to brake but was unable to stop on time and knock against vehicle b. My front portion was damaged and no injury involved.

Taxi Voucher No.:

**DECLARATION**

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MOHAMED SHARIL BIN SATAR

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

22 January 2021 at 4:09 PM

Date/Time:

22 January 2021 at 4:09 PM



REPUBLIC OF SINGAPORE

DRIVING LICENCE



Licence Number: S7040031F

Name:

KOH TIONG KHENG

Birth Date: 07 Nov 1970

Issue Date: 07 Feb 2015



002394310C



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7040031F



Name

KOH TIONG KHENG



许忠庚

Race

CHINESE

Date of Birth

07-11-1970

Sex

M

Country of Birth

SINGAPORE







HOTLINE TEL: (65) 6419-3000

## COVER NOTE

|   |  |                      |                               |
|---|--|----------------------|-------------------------------|
| Cover Note No.  | 100882531                                  | Date:                | 26 Jan 2021                   |
| The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder  |  |                      |                               |
| <b>Schedule</b>   |  |                      |                               |
| Policyholder  | Daimler Fleet Management Singapore Pte Ltd |                      |                               |
| Age Condition   | N/A  | Registration No      | SLC532Z                       |
| Policy Type   | COMPREHENSIVE MOTOR                        | Make/Model           | Mercedes Benz C200 Avantgarde |
| Effective Date  | 01 Jan 2021                                | CC/Tonnage           | 1991.00                       |
| Expiry Date   | 31 Dec 2021                                | Engine No            | 27492030577080                |
| Hire Purchase Company   | NA   | Chassis No           | WDD2050422R159732             |
|   |  | Year of Registration | 2016                          |
| <p><b>This policy is subject to driver's age condition. The policy will indemnify the insured or any authorised driver only if he/she meets the age condition. Please refer to policy terms and conditions.</b></p> <p>Usage of vehicle only for the following purposes:</p> <ol style="list-style-type: none"><li>1. Use only for social, domestic and pleasure purposes and for the Policyholder's business.</li><li>2. Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes.</li></ol> <p>Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.</p> <p>The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.</p> |  |                      |                               |
| MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)   |  |                      |                               |
| MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960   |  |                      |                               |
| ROAD TRANSPORT ACT, 1987 (MALAYSIA)   |  |                      |                               |
| MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)   |  |                      |                               |
| <b>CERTIFICATE OF INSURANCE</b>   |  |                      |                               |
| I / We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third- Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).  |  |                      |                               |

Issued in Singapore

AIG Asia Pacific Insurance PTE. LTD.

**IMPORTANT NOTICE**  
**THIS COVER NOTE IS VALID**  
**FOR 60 DAYS FROM THE**  
**FIRST DAY OF THE POLICY**  
**PERIOD.**

AUTHORISED REPRESENTATIVE



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16  
AIG BUILDING  
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2021

## ESTIMATE

NO : QUOT202101-000059(00)

DATE : 26/01/2021

POLICY NO : 999995580

VEH REG NO : SLC532Z

MAKE/MODEL : MERCEDES BENZ C200  
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050422R159732

ENGINE NO : 27492030577080

REG. DATE : 2016

## Estimate Repair Cost to Vehicle No : SLC532Z

| Description   | Quantity | Unit Price | Amount      |
|---|----------|------------|-------------|
|   |          | S\$        | S\$         |
| <b>PARTS</b>  |          |            |             |
| 1 Bonnet  | 1 Bu     | 1,290.00   | 1,290.00 ✓  |
| 2 Bonnet hinges - RH / LH                                       | 1        | 135.00     | 135.00 X    |
| 3 Bonnet Insulator clips  | 10       | 5.50       | 55.00 30.00 |
| 4 Support panel   | 1        | 480.00     | 480.00 ✓    |
| 5 Front grille  | 1        | 120.00     | 120.00 ✓    |
| 6 Front grille support  | 1        | 195.00     | 195.00 ✓    |
| 7 Front grille beam   | 1        | 205.00     | 205.00 2    |
| 8 Front grille beam chrome                                      | 2 116    | 58.00      | 232.00 ✓    |
| 9 Front grille centre logo                                      | 1        | 118.00     | 118.00 ✓    |
| 10 Front grille center logo base                                | 1        | 62.00      | 62.00 X     |
| 11 Headlamp assy -- RH / LH                                     | 2        | 2,750.00   | 5,500.00 ✓  |
| 12 Front bumper   | 1        | 980.00     | 980.00 ✓    |
| 13 Front bumper reinforcement                                   | 1        | 325.00     | 325.00 2    |
| 14 Front bumper sponge  | 1        | 155.00     | 155.00 2    |
| 15 Front bumper side retainer - RH / LH                         | 2        | 38.00      | 76.00 ✓     |
| 16 Front bumper inside part - center                            | 1        | 78.00      | 78.00 X     |
| 17 Front bumper inside parts - RH / LH                          | 2        | 72.00      | 144.00 2    |
| 18 Front bumper lower grille                                    | 1        | 98.00      | 98.00 X     |
| 19 Front bumper lower chrome                                    | 1        | 135.00     | 135.00 X    |
| 20 Front bumper fog lamp cover                                  | 1        | 58.00      | 58.00 ✓     |
| 21 Front bumper sensor  | 2        | 138.00     | 276.00 24   |
| 22 Front bumper sensor seals                                    | 6        | 8.00       | 48.00 2     |
| 23 Front bumper clips   | 15       | 5.50       | 82.50 ✓     |
| 24 Front fender - RH / LH                                       | 2        | 620.00     | 1,240.00 ✓  |
| 25 Air-con condenser  | 1        | 950.00     | 950.00 X    |
| 26 Front number plate garnish                                   | 1        | 98.00      | 98.00 ✓     |
|   |          |            | 13,411.50   |
|   |          | Add 10%    | 1,341.15    |
|   |          |            | 14,752.65   |
| <b>SPECIAL NET</b>  |          |            |             |
| 27 Front number plate   | 1        | 40.00      | 40.00 ✓     |
|   |          |            | 40.00       |
| <b>LABOUR</b>   |          |            |             |
| 28 To remove and refit air-con condenser and refill air-con gas | 1        | 150.00     | 150.00 100  |





# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16  
AIG BUILDING  
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2021

## ESTIMATE

NO : QUOT202101-000059(00)

DATE : 26/01/2021

POLICY NO : 999995580

VEH REG NO : SLC532Z

MAKE/MODEL : MERCEDES BENZ C200  
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050422R159732

ENGINE NO : 27492030577080

REG. DATE : 2016

## Estimate Repair Cost to Vehicle No : SLC532Z

| Description  | Quantity | Unit Price   | Amount        |
|--|----------|--------------|---------------|
|  |          | S\$          | S\$           |
| 29 To remove and refit front bumper sensor   | 1        | 100.00       | 100.00        |
| 30 To check and rectify wiring system  | 1        | 80.00        | 80.00         |
| 31 To panel beat and straighten, both side front fender inner panel, front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same | 1        | 1,200.00     | 1,200.00      |
| 32 To putty and spray paint on affected areas  | 1        | 1,500.00     | 1,500.00      |
| 33 To reset and reprogramme headlamp fault code  | 1        | 350.00       | 350.00        |
|  |          |              | 3,380.00      |
|  |          | TOTAL        | S\$ 18,172.65 |
|  |          | ADD GST @ 7% | 1,272.09      |
|  |          | GRAND TOTAL  | S\$ 19,444.74 |

SINGAPORE DOLLAR NINETEEN THOUSAND FOUR HUNDRED FORTY-FOUR AND CENTS SEVENTY-FOUR ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO

CLAIM TYPE OWN DAMAGE

ACCIDENT DATE 22/01/2021

## ESTIMATE

NO : QUOT202101-000059(00)

DATE : 02/02/2021

POLICY NO : 999995580

VEH REG NO : SLC532Z

MAKE/MODEL : MERCEDES BENZ C200  
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050422R159732

ENGINE NO : 27492030577080

REG DATE : 2016

## Estimate Repair Cost to Vehicle No : SLC532Z

| Description                 | Quantity | Unit Price   | Amount      |
|-----------------------------|----------|--------------|-------------|
|                             |          | SS           | SS          |
| SUPPLEMENTARY PARTS         |          |              |             |
| 1 Bonnet actuator - RH / LH | 2        | 165.00       | 330.00 ✓    |
| 2 Front bumper radar sensor | 1        | 780.00       | 780.00 ✓    |
| 3 Radiator spare tank       | 1        | 95.00        | 95.00 ✓     |
|                             |          |              | 1,205.00    |
|                             |          | Add 10%      | 120.50      |
|                             |          |              | 1,325.50    |
|                             |          | TOTAL        | SS 1,325.50 |
|                             |          | ADD GST @ 7% | 92.79       |
|                             |          | GRAND TOTAL  | SS 1,418.29 |

SINGAPORE DOLLAR ONE THOUSAND FOUR HUNDRED EIGHTEEN AND CENTS TWENTY-NINE ONLY

parts : \$ 12,487.20

SN : 120-00

Labour : 1,830.00

Supp : 1,325.50

\$ 15,762.70

XS

1,700.00

\$ 14,062.70

7%

984.38

FOR TONG LUCK AUTO PTE LTD

\$ 15,047.08