



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2021

ESTIMATE

NO : QUOT202101-000059(00)

DATE : 02/02/2021

POLICY NO : 999995580

VEH REG NO : SLC532Z

MAKE/MODEL : MERCEDES BENZ C200
AVANTGARDE (R17 LED)

CHASSIS NO : WDD2050422R159732

ENGINE NO : 27492030577080

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : SLC532Z

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Bonnet actuator - RH / LH	2	165.00	330.00 ✓
2 Front bumper radar sensor	1	780.00	780.00 ✓
3 Radiator spare tank	1	95.00	95.00 ✓
			1,205.00
		Add 10%	120.50
			1,325.50
		TOTAL	S\$ 1,325.50
		ADD GST @ 7%	92.79
		GRAND TOTAL	S\$ 1,418.29

SINGAPORE DOLLAR ONE THOUSAND FOUR HUNDRED EIGHTEEN AND CENTS TWENTY-NINE ONLY