

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

VEHICLE No: YN 3366E

LKK Hsiao Tony

Not Authorized

LKK

26/1/21

2/5 @ 6000

S.NETT

5 days

1PC	REAR TAILGATE WOODEN	CNA	\$3,800.00	✓ 2000
2PCS	REAR TAILGATE WOODEN BRACKETS @\$250.00	Bent	\$500.00	✓ 400
1PC	REAR TAILGATE WOODEN STEEL PLATE	n	\$800.00	X
1SET	REAR TAILGATE '60KM/H & 24 PAX' STICKER	nel	\$20.00	✓
1SET	REAR TAILGATE WOODEN 'COMPANY' STICKER	nel	\$680.00	400
1PC	REAR TAILGATE LOWER WOODEN	SVC	\$1,200.00	X
1PC	TAILLAMP N/S	CNA	\$190.00	✓
1PC	REAR STEP WOODEN CENTRE	CNA	\$1,000.00	500
1PC	REAR CHASSIS WOODEN N/S	CNA	\$3,200.00	2000
1PC	REAR CHASSIS WOODEN BRACKET N/S	SVC	\$500.00	X
1PC	REAR STEP LOWER BRACKET	Bent	\$1,500.00	800
1PC	REAR SAFETY BAR	11	\$1,800.00	X
			\$14,390.00	

TO CHECK WIRING

\$50.00 20

TO SPRAY RUST PROOFING

11 \$50.00 X

TO LIFT UP CARGO DECK FOR REPLACED CHASSIS WOODEN

\$800.00

LABOUR FOR PANEL BEATING & REPLACED PARTS

\$1,200.00 } 800

TO PUTTY & SPRAT PAINTING

\$680.00 380

TOTAL \$17,170.00

P-6310

L-1200

7510

288

6008

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts' prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: