

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0084/2021/GW
DATE : 26/01/2021
WIP :

Jasper.

P/P = 18500.40.

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : PREMIUM AUTOMOBILES PTE LTD
ADDRESS : 55 UBI ROAD 1
SINGAPORE 408699
TELEPHONE :
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : SLH 2161 X
MODEL CODE : Q5 2.0 TFSI QU
MODEL YEAR : 26/10/2016
ENGINE NO : CNC 176494
CHASSIS NO : WAUZZZ8R1HA041311
MILEAGE :
DATE IN :
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Jan-21
PLACE OF ACCIDENT : 55 UBI ROAD 1

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLH 2161 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	X
2	TO REMOVE AND TRANSFER RHS FRONT FOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	Check Pricing ✓ 500.
3	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. TO RENEW RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. TO REPAIR RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,400.00	2000
4	TO REPAIR RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, DOOR COVERS, DOOR HANDLES, RHS REAR FENDER.	\$ 5,100.00	2600 ✓ 4x550 = 2200 Door Cover x 2 = 200 x 2 = 400 2600
5	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00	✓
6	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500 500
SUB TOTAL LABOUR CHARGES		\$ 12,260.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLH 2161 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER AND REAR BUMPER SPOILER.	X	\$ 2,400.00	550 550
8	TO RENEW RHS FRONT RIM AND RHS REAR RIM. TO CARRY OUT WHEEL ALIGNMENT.	S/N	\$ 320.00	✓
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES			: \$ 15,172.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLH 2161 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT FENDER-RH <i>Dented</i>	\$	1,002.00 ✓	\$801.60
2 FRONT FENDER ATTACHMENT PARTS-RH <i>new</i>	\$	67.00 +	
3 FRONT FENDER BRACE-RH <i>new</i>	\$	88.00 +	
4 FRONT FENDER CLOSING ELEMENT-RH <i>new</i>	\$	105.00 +	
5 FRONT WHEEL HOUSING LINER-RH <i>Not new</i>	\$	264.00 +	
6 FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>at</i>	\$	104.00 +	
7 FRONT DOOR-RH <i>Dented</i>	\$	4,085.00 ✓	\$3,268.00
8 FRONT DOOR OUTER SEAL-RH OUTER <i>new</i>	\$	205.00 ✓	\$164.00
9 BONDING AGENT	\$	49.00 +	
10 CLEANING SOLUTION <i>Not</i>	\$	68.00 +	
11 APPLICATOR <i>new</i>	\$	8.00 +	
12 FRONT DOOR ATTACHMENT PARTS <i>new</i>	\$	129.00 +	
13 FRONT DOOR CATCH-RH <i>Not new</i>	\$	146.00 +	
14 FRONT DATE PLATE FOR TYRE PRESSURE <i>new</i>	\$	30.00 ✓	\$24.00
15 FRONT DOOR HINGE-RH UPPER/LOWER <i>new</i>	\$	150.00 +	
16 FRONT DOOR COVER-RH <i>new</i>	\$	511.00 ✓	\$408.80
17 REAR DOOR <i>Dented</i>	\$	4,085.00 ✓	\$3,268.00
18 REAR DOOR OUTER SEAL-RH <i>new</i>	\$	205.00 ✓	\$164.00
19 BONDING AGENT	\$	49.00 +	
20 CLEANING SOLUTION <i>Not new</i>	\$	68.00 +	
SUB TOTAL SPARE PARTS	:	\$ 11,418.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLH 2161 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21	APPLICATOR <i>Not Nec</i>	\$	8.00	X
22	STONE CHIP PROTECTION FILM -RH INNER <i>Nec</i>	\$	78.00	✓ \$62.16
23	REAR DOOR ATTACHMENT PARTS-RH <i>new</i>	\$	124.00	+
24	REAR DOOR CATCH-RH <i>Damaged</i>	\$	146.00	✓ \$116.40
25	REAR SILL PANEL SEAL-RH <i>new</i>	\$	222.00	X
26	REAR DOOR SEAL INNER-RH <i>new</i>	\$	205.00	X
27	REAR DOOR COVER-RH <i>new</i>	\$	409.00	✓ \$326.80
28	REAR WHEEL HOUSING LINER-RH <i>new</i>	\$	264.00	X
29	REAR BUMPER <i>toin</i>	\$	1,798.00	✓ \$1,438.40
30	REAR BUMPER FIXING PARTS <i>new</i>	\$	166.00	X
31	REAR BUMPER SPOILER <i>new</i>	\$	866.00	X
32	REAR BUMPER GUIDE SECTION-RH <i>new</i>	\$	54.00	X
33	TAIL LIGHTS-RH <i>new</i>	\$	299.00	X
34	FRONT ALUMINIUM RIM-RH <i>new</i>	\$	1,652.00	X
35	REAR ALUMINIUM RIM-RH <i>lot</i>	\$	1,652.00	✓ \$1,321.60
36	SUNDRIES <i>Nec</i>	\$	300.00	→ 47.04
TOTAL SPARE PARTS		:	\$ 19,661.00	
TOTAL LABOUR CHARGES		:	\$ 15,172.00	
GRAND TOTAL		:	\$ 34,833.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King
SURVEYED DATE : 26/01/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 07 Days H.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Jasper



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Mr. Adrian Ling - Motor Claims Dept
 Tel: 6341 0055 / Fax: 6256 4315


Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/TP/0084/2021/CW
 29-Jan-21
 CHANG
 1 of 1
 SLH 2161 X
 AUDI Q5 2.0 TSF QU

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT FENDER LINING - RH <i>ok d</i>	\$ 185.00	✓ \$147.60
GRAND TOTAL		\$ 185.00	

For Premium Automobiles Pte Ltd

Adrian Ling
AS 02/01/21



Authorised Signature

PREMIUM AUTOMOBILES PTE LTD
 78 SHENTON WAY
 SINGAPORE 079120