

8 Kaki Bukit Ave 4 #08-45/46 Premier@ Kaki Bukit S415875
Tel: 6702 1555 Fax: 6702 1444 ROC No. : 201500047H

ESTIMATE

TO : MSIG	DATE : 21/1/2021
ATTENTION : MOTOR CLAIM DEPARTMENT	JOB TYPE : THIRD PARTY CLAIM
VEHICLE DETAILS	
VEHICLE NO. : SLT46X	ACCIDENT DETAIL
MAKE / MODEL : LEXUS NX300	DATE : 17/1/2021
CHASSIS NO. : JTJBARBZ502190708	TIME : 10:40
OWNER INSURANCE : NTUC	
POLICY NO. : 5109855704-01	
PERSON INCHARGE : Yvette T: 6702 1555 D: 9296 9185 F: 6702 1444 yvette@skauto.com.sg	

CLAIM DETAIL : LIST PRICE (\$\$)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER ?	1	\$ 1,061.00	\$ 1,061.00
2	FRONT BUMPER WIPER NOZZLE RH X	1	\$ 143.00	\$ 143.00
3	FRONT BUMPER LED LAMP RH X	1	\$ 2,040.00	\$ 2,040.00
4	FRONT HEADLIGHT / cut	1	\$ 3,930.00	\$ 3,930.00
TOTAL PRICE : \$				7,174.00
LIST LESS 10% : \$				717.40
SUB TOTAL PRICE : \$				<u>6,456.60</u>

CLAIM DETAIL : PARTS S/NETT

S/N	DESCRIPTION	QTY	UNIT S/N PRICE	TOTAL S/N PRICE
1	FRONT BUMPER CLIPS SET / MC	1	\$ 50.00	\$ 50.00
S/N TOTAL PRICE : \$				<u>50.00</u>

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	DESCRIPTION	PRICE	ADJUST
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 400.00	200
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 400.00	200 250.
3	TO APPLY ANTI-RUST & TUFF KOTE	\$ 150.00	X NN.
4	COMPUTERISE DIAGNOSTIC CHECK AND PARAMETER SETTINGS FOR (FRONT HEADLIGHT), (FRONT BUMPER LED LAMP)	\$ 380.00	30.
LABOUR TOTAL PRICE : \$		<u>1,330.00</u>	

ESTIMATE REPORT

TOTAL PARTS PRICE : \$	6,506.60
TOTAL LABOUR PRICE : \$	1,330.00
TOTAL AMOUNT : \$	7,836.60

APPROVED DETAILS

NO. OF REPAIR DAYS :

P & P OR LUMP SUM :

SURVEYED BY :

CONTACT NUMBER :

E-MAIL :

2
Impass repair / After repair photos.
Gino Qian
8288 0282
27/1/2021.

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: