

ORIGINAL

Co. Reg: 20135118W

Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883

• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date : 27/1/2021

Total Pages : 2

TO: China Taiping Insurance (S) Pte Ltd
 3 Anson Rd, #16-00
 Springleaf Tower
 Singapore 079909

Denise

Our Customer : Soh Weicong

Vehicle No : SKX3133Z

Model : HONDA / SHUTTLE 1.5G CVT

Manufacture Year : 2015

Date of Accident : 25/1/2021

Total Estimate Repair Days : 14

Attn : Motor Claim Department

Email : claimsdept@sg.cntaiping.com

Re: Repair Estimate For Third Party Claim against : GBJ8234M

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>Replaced</i>	1	\$1,150.60	\$1,150.60	✓
2	Rear bumper clips <i>re</i>	11	\$3.50	\$38.50	✓
3	Rear bumper tow cover <i>Replaced</i>	1	\$16.50	\$16.50	✓
4	Rear bumper RH & LH reflector <i>new</i>	2	\$45.00	\$90.00	+
5	Rear bumper garnish RH & LH <i>new</i>	2	\$45.00	\$90.00	+
6	Rear bumper under plastic RH & LH <i>new</i>	2	\$38.70	\$77.40	+
7	Rear bumper under plastic clips <i>new</i>	10	\$3.50	\$35.00	+
8	Rear bumper parking sensor <i>Replaced</i>	1	\$148.40	\$148.40	✓
9	Rear bumper side retainer RH & LH <i>re</i>	2	\$24.90	\$49.80	✓
10	Rear buzzer <i>Replaced</i>	1	\$80.00	\$80.00	✓
11	RH Taillamp <i>cut</i>	1	\$520.50	\$520.50	✓
12	RH Taillamp clips <i>re</i>	2	\$3.50	\$7.00	✓
13	LH taillamp <i>Replaced</i>	1	\$520.50	\$520.50	✓
14	LH taillamp clips <i>re</i>	2	\$3.50	\$7.00	✓
15	Tailgate <i>Replaced</i>	1	\$1,193.00	\$1,193.00	✓
16	Tailgate outer garnish <i>Replaced</i>	1	\$383.10	\$383.10	✓
17	Tailgate reflector RH & LH <i>cut</i>	2	\$395.00	\$790.00	✓
18	Tailgate number plate lamp <i>new</i>	2	\$38.50	\$77.00	+
19	Tailgate reverse camera <i>new</i>	1	\$1,150.00	\$1,150.00	+
20	Tailgate emblem <i>new</i>	1	\$38.00	\$38.00	✓
21	Shuttle lettering <i>new</i>	1	\$55.00	\$55.00	✓
22	Tailgate wiper arm <i>cut</i>	1	\$85.50	\$85.50	✓
23	Tailgate rear wiper arm cover <i>cut</i>	1	\$10.50	\$10.50	✓
24	Tailgate rear wiper arm motor <i>Replaced</i>	1	\$390.00	\$390.00	✓
25	Tailgate lock <i>Replaced</i>	1	\$187.10	\$187.10	✓
26	Tailgate catch <i>new</i>	1	\$27.50	\$27.50	+
27	Tailgate inner trim board <i>Replaced</i>	1	\$320.00	\$320.00	✓
28	Tailgate damper <i>new</i> Damaged	1	\$165.00	\$165.00	✓
29	Tailgate open/close pocket <i>Replaced</i>	1	\$25.00	\$25.00	✓
30	Tailgate windscreen <i>Shattered</i>	1	\$1,210.10	\$1,210.10	✓
31	Tailgate windscreen moulding <i>re</i>	1	\$120.00	\$120.00	✓
32	Tailgate weatherstrip <i>cut</i>	1	\$168.50	\$168.50	✓
33	End panel <i>Replaced</i>	1	\$560.80	\$560.80	✓
34	End panel top garnish <i>cut</i>	1	\$155.50	\$155.50	✓
35	End panel inner trim <i>Replaced</i>	1	\$88.60	\$88.60	✓
36	Floor panel <i>Replaced</i>	1	\$1,980.00	\$1,980.00	✓ 1056
37	Floor panel foam board <i>Replaced</i>	1		286.60 \$0.00	✓
38	Floor panel luggage compartment <i>Replaced</i>	1		180.93 \$0.00	✓
39	Luggage compartment wooden board <i>Replaced</i>	1		80.40 \$0.00	✓
40	LH rear fender inner trim - lower <i>Replaced</i>	1		324.65 \$0.00	✓

ORIGINAL



Co. Reg: 20135118W

Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883

• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

41	RH rear fender inner trim - lower	1		324.65	\$0.00	X
42	Tailgate keyless switch	1		108	\$0.00	X
43	Tailgate keyless sensor	1		60.80	\$0.00	X
Sub Total					\$12,011.40	
Less 20%					\$2,402.28	
Sub Total 1					\$9,609.12	
Total Spare Parts					\$9,609.12	
B.	Spare parts (S/nett)					
1	Rear number plate	1	\$50.00	\$50.00		✓
2	Windscreen sealant	1	\$25.00	\$25.00		✓
3	Windscreen seal	2	\$25.00	\$50.00		✓
4	Floor panel insulation padding	1				X
Sub Total					\$125.00	
Sub Total 2					\$9,484.12	
C.	Labour					
1	To knock & straighten the damaged panels, remove & renew damaged parts, adjust & realign the same			\$1,500.00		1300
2	To mount vehicle on Car O liner bench to obtain cross and parallel measurement and correct to manufacturer specification			\$300.00		200
3	To remove and refit the upholstery to assist in workload			\$180.00		✓
4	To rust proof all affected areas			\$180.00		120
5	To apply under coating			\$120.00		80
6	To re-install rear parking sensor			\$120.00		50
7	To check lighting and all wiring			\$120.00		30
8	To transfer tailgate trimmings and lock mechanism to assist workload			\$180.00		80
9	Labour to apply insulation padding			\$180.00		X
10	To re-route tailgate wiring			\$80.00		60
12	To remove and renew rear windscreen glass			\$120.00		✓
13	To spray paint rear bumper, tailgate, floor panel and end panel			\$1,200.00		1000
14	Interior cleaning and cleaning of shattered glasses			\$80.00		50
Total Labour					\$4,360.00	
Total Repair Cost					\$13,969.12	
* The above quoted are exclusive of GST.						

Yours faithfully,

Darla
f Auto N Cars Services Pte Ltd



9 days

Surveyor's Details	
Name	Adrian
Contact	96893735
Survey Date	27/01/21
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	[Signature]

09 Days
Supplementary: 701.60
Total: 12476.88
H/S: 9950

3270



Co. Reg: 20135118W

Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883

• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date : 28/1/2021

TO: China Taiping Insurance (S) Pte Ltd
3 Anson Rd, #16-00
Springleaf Tower
Singapore 079909

Total Pages : 2

Our Customer : Soh Weicong

Vehicle No : SKX3133Z

Model : HONDA / SHUTTLE 1.5G CVT

Manufacture Year : 2015

Date of Accident : 25/1/2021

Total Estimate Repair Days : 14

Attn : Motor Claim Department

Email : claimsdept@sg.cntaiping.com

Re: Supplementary Repair Estimate For Third Party Claim against : GBJ8234M

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	LH rear taillamp panel <i>3 Dented</i>	1	\$163.50	\$163.50	✓
2	RH rear taillamp panel	1	\$163.50	\$163.50	✓
	Sub Total			\$327.00	
	Less 20%			\$65.40	
	Sub Total 1			\$261.60	
B.	Spare parts (S/nett)				
1	Body Sealant <i>Nu</i>	1	\$80.00	\$80.00	✓
	Sub Total			\$80.00	
	Total Spare Parts			\$341.60	
C.	Labour				
1	Labour to cut and replace taillamp panel <i>360</i>			\$360.00	<i>300</i>
2	Labour to apply body sealant <i>Nu</i>			\$120.00	<i>60</i>
	Total Labour			\$480.00	
	Total Repair Cost			\$821.60	
	* The above quoted are exclusive of GST.				

Yours faithfully,

Darla

f Auto N Cars Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

Supplementary : 701.60 *Adrian*
28/01/21.
R.S.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: