

✓ car in

Trans-cab Auto Services Pte Ltd

AAD2101-076

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX4062P

Not Notarised
Recovery Blegain

Vehicle No.:

SMX4062P

Chassis No.:

JTDKB3FU703091409

Vehicle Make:

TOYOTA

Vehicle Model:

2-5 JAN 2021

PRIUS GEN 4

Date of Accident :

21/01/2021

Third Party Insurer :

TOKIO

Date of Registration :

11/01/2021

PART	LIST	PRICE	STATUS
1 FRONT FENDER EMBLEM LH	\$ B 54.60	54.60	X
1 COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$ B 100.40	100.40	✓
1 MIRROR ASSY, OUTER REAR VIEW, LH	\$ B 1,339.30	1,339.30	✓
1 MOULDING, FRONT DOOR WINDOW FRAME, FRONT LH	\$ B 38.60	38.60	✓
1 MOULDING, FRONT DOOR WINDOW FRAME, REAR LH	\$ B 56.50	56.50	✓
1 MOULDING, FRONT DOOR WINDOW FRAME, REAR RH	\$ B 56.50	56.50	✓
1 MOULDING ASSY, FRONT DOOR BELT, LH	\$ B 92.00	92.00	✓
1 MOULDING ASSY, FRONT DOOR BELT, LH	\$ B 92.00	92.00	X
1 WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH	\$ SVC 76.40	76.40	? X
1 HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$ B 390.60	390.60	X
1 MOULDING, REAR DOOR WINDOW FRAME, REAR LH	\$ B 38.60	38.60	✓
1 MOULDING, REAR DOOR WINDOW FRAME, FRONT LH	\$ B 56.50	56.50	✓
1 MOULDING, REAR DOOR WINDOW FRAME, FRONT RH	\$ B 56.50	56.50	✓
1 MOULDING ASSY, REAR DOOR BELT, LH	\$ B 113.50	113.50	✓
1 MOULDING ASSY, REAR DOOR BELT, LH	\$ B 113.50	113.50	X
1 WEATHERSTRIP, REAR DOOR QUARTER WINDOW, LH	\$ SVC 49.30	49.30	? X
1 HANDLE ASSY, REAR DOOR OUTSIDE, LH	\$ B 97.40	97.40	X X
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$ B 594.80	594.80	✓
1 MOULDING, REAR DOOR WINDOW FRAME, REAR LH	\$ SVC 38.60	38.60	? X
1 LENS & BODY, REAR COMBINATION LAMP, LH	\$ B 339.60	339.60	✓
1 COVER, REAR BUMPER	\$ B 485.60	485.60	✓
TOTAL	\$ 4,280.80	4,280.80	
25%	\$ 1,070.20	1,070.20	
	\$ 3,210.60	3,210.60	

Special Nett

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

AAD2101-076

SMX4062P

1 FENDER CLIP		\$	na	65.00	X
1 FENDER LINER CLIP		\$	na	65.00	X
1 FRT BUMPER CLIP		\$	na	65.00	X
1 SEAM SEALANT		\$	na	200.00	X
1 TAIL LAMP CLIP		\$	na	70.00	2da
1 FRONT PILLAR GARNISH CLIP		\$	na	60.00	X
2SET DOOR WEATHERSTRIP CLIP		\$	na	130.00	X
1 FRT DOOR STICKER TRANSCAB		\$	na	100.00	X
2 HUB CAP		\$	na	423.00	X
1SET CLIP, ROCKER PANEL MOULDING		\$	na	65.00	X
TOTAL		\$		1,243.00	

TOTAL PARTS \$ 4,453.60

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ na 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 1,400.00 400

Putty And Spray Painting Of The Affected Portion. \$ 1,400.00 880

To Rust-Proofing and apply undercoat Of The Affected Areas. \$ 240.00 X

To Check Electrical Lighting Concerned. \$ 170.00 20

TOTAL \$ 3,590.00

Over All Total \$ 8,043.60

(PART-BY-PART) Repair Days

20 days

5 days

LEK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*Acknowledged by Repairer
 Signature:
 :