

ASS. REC. BY:

REF: TMI / CC3/TMI21001257/Ktf3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s Trans Cab

of _____

Insured: _____

Policy No. ML000183

Claims No. M2100440

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: +B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMX 4062P Yr Regn: 011 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Prime Mover /

Truck / Trailer or _____

Make: Toy Prius c.c. 1788

Colour M. White Silver A/C: Insured / Std / NI / NA

Sp. Reading 1215 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU703091409

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rlm / STD / Rlm or

Tyre Size: F: 195/85R15

R: _____

BS: OUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 11/1/21 D.O.I. 25/1/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The external plastic parts found damaged

The UIC / Chassis frame / Body Structure affected due to collision.

at the time of inspection. The cause of damage

due to external sources.

Date / Time Action / Instruction

Confirm \$3,911.20, 5 working days

RED: 4132.4; 51%

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trlp: 1

Survey Fee:

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Transportation:

\$ - RS. \$ _____

Fuel:

Others:

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

✓ car in

Trans-cab Auto Services Pte Ltd

AAD2101-076

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX4062P

Not Not hash
Pekony Blegain

Vehicle No.:

SMX4062P

Chassis No.:

JTDKB3FU703091409

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS GEN 4

25 JAN 2021

Date of Accident :

21/01/2021

Third Party Insurer :

TOKIO

Date of Registration :

11/01/2021

PART	LIST	PRICE	STATUS
1 FRONT FENDER EMBLEM LH	Sm	54.60	X
1 COVER SUB-ASSY, FRONT PILLAR, UPR LH	B	100.40	✓
1 MIRROR ASSY, OUTER REAR VIEW, LH	B	1,339.30	✓
1 MOULDING, FRONT DOOR WINDOW FRAME, FRONT LH	B	38.60	✓
1 MOULDING, FRONT DOOR WINDOW FRAME, REAR LH	B	56.50	✓
1 MOULDING, FRONT DOOR WINDOW FRAME, REAR RH	B	56.50	✓
1 MOULDING ASSY, FRONT DOOR BELT, LH	B	92.00	✓
1 MOULDING ASSY, FRONT DOOR BELT, LH	Perman B	92.00	X
1 WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH		76.40	?
1 HANDLE ASSY, FRONT DOOR OUTSIDE, LH	Sm	390.60	X
1 MOULDING, REAR DOOR WINDOW FRAME, REAR LH	B	38.60	✓
1 MOULDING, REAR DOOR WINDOW FRAME, FRONT LH	B	56.50	✓
1 MOULDING, REAR DOOR WINDOW FRAME, FRONT RH	B	56.50	✓
1 MOULDING ASSY, REAR DOOR BELT, LH	B	113.50	✓
1 MOULDING ASSY, REAR DOOR BELT, LH	Perman	113.50	X
1 WEATHERSTRIP, REAR DOOR QUARTER WINDOW, LH		49.30	?
1 HANDLE ASSY, REAR DOOR OUTSIDE, LH	Sm	97.40	X
1 MOULDING ASSY, BODY ROCKER PANEL, LH	B	594.80	✓
1 MOULDING, REAR DOOR WINDOW FRAME, REAR LH		38.60	?
1 LENS & BODY, REAR COMBINATION LAMP, LH	B	339.60	✓
1 COVER, REAR BUMPER	B	485.60	✓
TOTAL		\$ 4,280.80	
25%		\$ 1,070.20	
		\$ 3,210.60	

Special Nett

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

AAD2101-076

SMX4062P

1 FENDER CLIP	Video Report No	\$	na	65.00	X
1 FENDER LINER CLIP	CP27619 21/02/27	\$	na	65.00	X
1 FRT BUMPER CLIP	Address	\$	na	65.00	X
1 SEAM SEALANT	AFT BLK 311 UBI AVENUE	\$	na	200.00	X
1 TAIL LAMP CLIP	400311	\$	na	70.00	2000
1 FRONT PILLAR GARNISH CLIP	Contact No	\$	na	60.00	X
2SET DOOR WEATHERSTRIP CLIP	Home/Office	\$	na	130.00	X
1 FRT DOOR STICKER TRANSCAB	Email Address	\$	na	100.00	X
2 HUB CAP		\$	na	423.00	X
1SET CLIP, ROCKER PANEL MOULDING	Sex	\$	na	65.00	X
TOTAL	Age	\$		1,243.00	
	Male	\$			
	Female	\$			
	Language				
	Drigress				
	Location	TOTAL PARTS	\$	4,453.60	

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 4000

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 8801

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 201

TOTAL \$ 3,590.00

Over All Total \$ 8,043.60

(PART-BY-PART) Repair Days

20 days

5 days

LEK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 :



**SINGAPORE
POLICE FORCE**



F/20210122/2012

1 of 2

Report No. F/20210122/2012

POLICE REPORT (NP299)

Police Station Of Origin
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Date/Time Report Made 22/01/2021 09:59	Vide Report No. G/20210121/0127	Station Diary No. 27
Name Of Informant SEAH LEE CHEONG	Address APT BLK 311 UBI AVENUE 1 #09-377 SINGAPORE 400311	
ID Type / ID No. NRIC NO / S1176814H	Contact No. Home/Office	Mobile 93886065
Nationality SINGAPORE CITIZEN	Email Address	
Occupation PHV DRIVER	Sex Male	Age 64
Institution/School Name	Date of Birth 25/09/1956	Race Chinese
Date/Time Of Incident 21/01/2021 17:30 - 21/01/2021 18:00	Location Of Incident APT BLK 311 UBI AVENUE 1 KAMPONG UBI GREENVILLE SINGAPORE 400311 Open-air HDB carpark between Blk 311 and Blk 315 Ubi Ave 1 (lot 252)	

Brief details.

252 *jc*

On 21/01/2021 at or about 1700hrs, I parked my silver car TOYOTA PRIUS 5-door hatchback 'SMX4062P' inside lot number 252 behind Blk 311 Ubi Ave 1. I then went to do some shopping nearby before returning home. On the same day between 1730hrs and 1800hrs I returned to my car and was shocked to find that my car was damaged by the heat of a burning motor-van that was parked besides

Signature Of Officer Recording The Report: F / SI MOHAMMED BIN ZAINOL <i>[Signature]</i>	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 22/01/2021 09:59
Officer In-Charge Of Case: F / Ang Mo Kio Police Divisional Investigation Branch / Insp ELANGO GOPALAN Contact No.: 62181343	Classification Of Case:

Authentication Stamp





my aforesaid car. There was already a big crowd gathering and both the Police and Civil Defence were at the said fire scene. As a result of the said fire, my car sustained serious damages to its left side. I estimate that the cost of damages to be at least S10,000. Throughout the whole fire incident I do not know who is the owner / driver of the burnt motor-van. I cannot recall if the motor-van was already parked at the lot (250) near to mine or not when I first parked at the said carpark. The motor-van number is 'GBD8221G'. I do not know the colour, make and model of the said motor-van.

SCDF investigator "Rahman" (HP:90211564) has since contacted me with regards to this fire case. I am lodging this cover report as directed by my leasing Company 'TRANS LEASING PTE LTD', for the purpose of their insurance claiming against the other party. The police in-charge for yesterday's incident is one Staff Sergeant Muhd Asri Bin Ishak from GEYLANG NEIGHBOURHOOD POLICE CENTRE, Tel: 65142744.

Signature Of Officer Recording The Report: F / SI MOHAMMED BIN ZAINOL	
Signature Of Interpreter: Not applicable	
Officer In-Charge Of Case: F / Ang Mo Kio Police Divisional Investigation Branch / Insp ELANGO GOPALAN Contact No.: 62181343	

Signature Of Informant:
Date/Time: 22/01/2021 09:59
Classification Of Case:

Authentication Stamp

