

CAR NO: SMK6066JWIP: 16144 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Turbocarger heat shield	? / SUPP		/ BT	98 070 529 80 40.80
2	Exhaust catalyst muffler	? / SUPP		/ BT	98 124 936 80 (TBA)
3	Exhaust system clamp	? / SUPP		/ REC Steve 29/1/91	98 091 486 80 93.60
4	Air conditioned freon tube	? / SUPP		/ BT	98 199 185 80 263.20
5	Air conditioned freon tube	? / SUPP		/ BT	98 082 518 80 (TBA)
6	Air conditioned freon tube	? / SUPP		/ BT	98 082 517 80 (TBA)
7	AIR INLET NECK WATER DEFLECTOR	? / SUPP		/ BR	98 890 141 80 77.60
8	FR BUMPER AIR VENTILAT BR DUCT RH	? / SUPP	(Inter comb. panel) / BR		98 142 079 80 \$ 94.40
9	BUMPER BRACKET SET	? / SUPP	(front panel inner) / BR		16 101 943 80 \$ 152.60
10	HL LH	? / SUPP	(Head lamp) / BR		98 020 415 80 \$ 569.60
11	FRONT BUMPER DEFLECTOR	? / SUPP	(chrome housing back) / BR		98 063 684 80 \$ 136.80
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		

MODEL: CASURVEYOR: STEVE