

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: UNITED OVERSEAS INSURANCE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING YP4349M [YOUR INSURED] & GBF6489D [OUR CLIENT]
ON 26/01/2021.

not Authorized
here
2/5 & 5000
the photo of the car
5 days.

ESTIMATED REPAIR COSTS FOR GBF6489D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	TAILGATE	\$ 1,789.24
1PC	TAILGATE LOGO	\$ 78.94
1PC	TAILGATE WINDSCREEN MOULDING	\$ 349.28
1PC	TAIL LAMP RH	\$ 556.97
1PC	TAIL LAMP PANEL RH	\$ 796.27
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$71.00 EACH	\$ 142.00
1PC	REAR FENDER RH	\$ 2,062.18
1PC	REAR FENDER INNER TRIM RH	\$ 492.34
1PC	REAR RIM RH	\$ 512.94
1PC	REAR WHEEL BEARING RH	\$ 336.39
1PC	REAR WHEEL BEARING HUB RH	\$ 392.41
1PC	REAR WHEEL SPRING LEAF RH	\$ 472.56
1PC	REAR AXLE	\$ 2,485.60
1PC	REAR SLIDING DOOR RH	\$ 1,982.37

PARTS SUM: \$ 12,449.49

PARTS LESS 25%: \$ 3,112.37

PARTS TOTAL: \$ 9,337.12

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY TAIL LAMP CLIPS	\$ 50.00
*	TO SUPPLY TAIL LAMP PANEL SEALANT	\$ 80.00
*	TO SUPPLY REAR FENDER SEALANT	\$ 80.00
*	TO SUPPLY REAR BUMPER CLIPS	\$ 50.00
*	TO SUPPLY REAR FENDER & SLIDING DOOR COMPANY STICKER	\$ 2,000.00
*	TO SUPPLY REAR FENDER ARC GARNISH	\$ 600.00
*	TO SUPPLY TAIL LAMP LOWER GARNISH	\$ 300.00
*	TO SUPPLY 70KM STICKER	\$ 50.00

*	TO SUPPLY REAR BUMPER	CFA	\$ 1,600.00	900 s/w
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	17	\$ 300.00	X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS		\$ 2,000.00	1080
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS		\$ 2,000.00	900
*	TO TUFF COAT DAMAGED AREAS		\$ 300.00	60
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	17	\$ 120.00	X
*	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	17	\$ 300.00	X
*	TO RNR REAR SLIDING DOOR TO FACILITATE REPAIRS		\$ 200.00	50
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS		\$ 200.00	20
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	17	\$ 300.00	X
*	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	m	\$ 120.00	X

LABOUR & S/N TOTAL: \$ 10,650.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 19,987.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3565-6
257

P-26742
1520

S/W-1120

L-2110
-6304.2