

# JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: UNITED OVERSEAS INSURANCE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING YP4349M [YOUR INSURED] & GBF6489D [OUR CLIENT]

ON 26/01/2021.

## ESTIMATED REPAIR COSTS FOR GBF6489D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	TAILGATE	\$ 1,789.24
1PC	TAILGATE LOGO	\$ 78.94
1PC	TAILGATE WINDSCREEN MOULDING	\$ 349.28
1PC	TAIL LAMP RH	\$ 556.97
1PC	TAIL LAMP PANEL RH	\$ 796.27
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$71.00 EACH	\$ 142.00
1PC	REAR FENDER RH	\$ 2,062.18
1PC	REAR FENDER INNER TRIM RH	\$ 492.34
1PC	REAR RIM RH	\$ 512.94
1PC	REAR WHEEL BEARING RH	\$ 336.39
1PC	REAR WHEEL BEARING HUB RH	\$ 392.41
1PC	REAR WHEEL SPRING LEAF RH	\$ 472.56
1PC	REAR AXLE	\$ 2,485.60
1PC	REAR SLIDING DOOR RH	\$ 1,982.37

**PARTS SUM:** \$ 12,449.49

**PARTS LESS 25%:** \$ 3,112.37

**PARTS TOTAL:** \$ 9,337.12

## LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY TAIL LAMP CLIPS	\$ 50.00
*	TO SUPPLY TAIL LAMP PANEL SEALANT	\$ 80.00
*	TO SUPPLY REAR FENDER SEALANT	\$ 80.00
*	TO SUPPLY REAR BUMPER CLIPS	\$ 50.00
*	TO SUPPLY REAR FENDER & SLIDING DOOR COMPANY STICKER	\$ 2,000.00
*	TO SUPPLY REAR FENDER ARC GARNISH	\$ 600.00
*	TO SUPPLY TAIL LAMP LOWER GARNISH	\$ 300.00
*	TO SUPPLY 70KM STICKER	\$ 50.00

*	TO SUPPLY REAR BUMPER	\$ 1,600.00
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	\$ 300.00
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,000.00
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,000.00
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$ 120.00
*	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 300.00
*	TO RNR REAR SLIDING DOOR TO FACILITATE REPAIRS	\$ 200.00
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00
*	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	\$ 120.00

**LABOUR & S/N TOTAL: \$ 10,650.00**

**GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 19,987.12**