



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI21001259/Uvd3e2 Date: 04/05/2021 Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YP 4349M	Veh. Inspected	GBF 6489D	
Policy No.		Coverage (\$)	0.00	
Claim No.	M11D11962102	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	26/01/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE DX (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KDH2015022089	Colour	WHITE	
Odometer	228131 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15	MICHELIN	6 mm	
L/H Front Tyre	195 R15	MICHELIN	6 mm	
R/H Rear Tyre	195 R15	MICHELIN	6 mm	
L/H Rear Tyre	195 R15	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/01/2021	Inspection Date	28/01/2021	
Survey held at	BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195			
Repairer	JWG INTERNATIONAL PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	