

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: UNITED OVERSEAS INSURANCE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING YP4349M [YOUR INSURED] & GBF6489D [OUR CLIENT]
ON 26/01/2021.

*not Authorized
here
d/s & S-350/
the photo of the car
5 days.*

ESTIMATED REPAIR COSTS FOR GBF6489D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	TAILGATE <i>~</i>	\$ 1,789.24 <i>X</i>
1PC	TAILGATE LOGO <i>neu 68.10</i>	\$ 78.94 <i>✓</i>
1PC	TAILGATE WINDSCREEN MOULDING <i>11</i>	\$ 349.28 <i>X</i>
1PC	TAIL LAMP RH <i>320 450</i>	\$ 556.97 <i>—</i>
1PC	TAIL LAMP PANEL RH <i>~</i>	\$ 796.27 <i>X</i>
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$71.00 EACH <i>11</i>	\$ 142.00 <i>X</i>
1PC	REAR FENDER RH <i>body 1645.10</i>	\$ 2,062.18 <i>—</i>
1PC	REAR FENDER INNER TRIM RH <i>11</i>	\$ 492.34 <i>X</i>
1PC	REAR RIM RH <i>11</i>	\$ 512.94 <i>X</i>
1PC	REAR WHEEL BEARING RH <i>11</i>	\$ 336.39 <i>X</i>
1PC	REAR WHEEL BEARING HUB RH <i>11</i>	\$ 392.41 <i>X</i>
1PC	REAR WHEEL SPRING LEAF RH <i>11</i>	\$ 472.56 <i>X</i>
1PC	REAR AXLE <i>11</i>	\$ 2,485.60 <i>X</i>
1PC	REAR SLIDING DOOR RH <i>DD / 2017 1462.40</i>	\$ 1,982.37 <i>—</i>

PARTS SUM: \$ 12,449.49

PARTS LESS 25%: \$ 3,112.37

PARTS TOTAL: \$ 9,337.12

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY TAIL LAMP CLIPS <i>11</i>	\$ 50.00 <i>X</i>
*	TO SUPPLY TAIL LAMP PANEL SEALANT <i>11</i>	\$ 80.00 <i>X</i>
*	TO SUPPLY REAR FENDER SEALANT <i>11</i>	\$ 80.00 <i>X</i>
*	TO SUPPLY REAR BUMPER CLIPS <i>neu</i>	\$ 50.00 <i>✓</i>
*	TO SUPPLY REAR FENDER & SLIDING DOOR COMPANY STICKER <i>neu</i>	\$ 2,000.00 <i>400</i>
*	TO SUPPLY REAR FENDER ARC GARNISH <i>neu</i>	\$ 600.00 <i>380</i>
*	TO SUPPLY TAIL LAMP LOWER GARNISH <i>neu</i>	\$ 300.00 <i>180</i>
*	TO SUPPLY 70KM STICKER <i>neu</i>	\$ 50.00 <i>10</i>

*	TO SUPPLY REAR BUMPER	CFQ	\$ 1,600.00	900 s/w
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	17	\$ 300.00	X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS		\$ 2,000.00	1080
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS		\$ 2,000.00	900
*	TO TUFF COAT DAMAGED AREAS		\$ 300.00	60
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	17	\$ 120.00	X
*	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	17	\$ 300.00	X
*	TO RNR REAR SLIDING DOOR TO FACILITATE REPAIRS		\$ 200.00	50
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS		\$ 200.00	20
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	17	\$ 300.00	X
*	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	m	\$ 120.00	X

LABOUR & S/N TOTAL: \$ 10,650.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 19,987.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3565-6
LS7

P-26742

S/W-1920

L-2110
6704.2