

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: Third Party

Date: 26.01.2021

Accident Date : 16.01.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair "Volkswagen Scirocco" Reg. No. SJZ6567L Claiming Against Your Insured Veh. No. SGM1006B		
1pc	Rear Bumper <i>1122-30</i>		<i>Actual</i> 1,200.00 ✓
8pcs	Rear Bumper Clips	5.00	<i>m</i> 40.00 ✓
	Less 10%		1,240.00
			124.00
			1,116.00
	Rear Number Plate		<i>Sen</i> 45.00 SN ✓
	To Transfer Rear Reverse Sensors, Rebores Sensor Hold & Rewiring etc		80.00 <i>501</i>
	Labour Charge - Panel Beating, Repairing Of Rear Bumper Reinforcement, Brackets and Parts Replacement		220.00 <i>2001</i>
	To Respray Affected Areas		250.00 <i>2001</i>
	Total :		<u>1,711.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: