



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III19015809/Qqd3e2-1	
			Date: 02/03/2021	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6393X	Veh. Inspected	SJE 2117P	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT19090079	Excess (\$)	0.00	
Assign From	CARINE KHEK	Assign Date	26/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA ROADSTER 2.0	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NCEC251126	Colour	RED	
Odometer	124475 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 ZR16	PETLAS	4 mm	
L/H Front Tyre	205/50 ZR16	PETLAS	4 mm	
R/H Rear Tyre	205/50 ZR16	BRIDGESTONE	5 mm	
L/H Rear Tyre	205/50 ZR16	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/09/2019	Inspection Date	06/09/2019	
Survey held at	160 SIN MING DRIVE #05-17			
Repairer	HIAP LEK AUTOMOBILE TRADING			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	