

Not Authored

8340-88

LAD2101-008

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SMX3266A

27 JAN 2021

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SMX3266A
JTDKB3FU903092514
TOYOTA
PRIUS GEN 4
23/01/2021
III
07/01/2021

- | | PART |
|---|-------------------------------------|
| 1 | COVER, REAR BUMPER |
| 1 | GUARD, REAR BUMPER, CENTER |
| 1 | REINFORCEMENT SUB-ASSY, REAR BUMPER |
| 1 | SEAL, REAR BUMPER SIDE, LH |
| 1 | RETAINER, REAR BUMPER SIDE, LH |
| 1 | REFLECTOR ASSY, REFLEX, LH |

	LIST	
\$	sm	485.60 X
\$	nd/ln	374.50 ✓
\$	ln	332.70 X
\$	ln	118.30 X
\$	ln	132.60 X
\$	ln	39.00 X
TOTAL \$		1,443.70
25% \$		360.93
\$		1,082.78

Special Nett

- | | |
|------|---------------------------|
| 1 | REAR BUMPER SIDE CLIP |
| 1SET | PARKING AID |
| 1SET | REAR BUMPER CLIP |
| 1 | REAR BUMPER PROTECTOR |
| 1 | REAR BUMPER RETAINER CLIP |

\$	nn	60.00 X
\$	ln	700.00 X
\$	nn	85.00 X
\$	nn	180.00 X
\$	nn	75.00 X
TOTAL \$		1,100.00

TOTAL PARTS \$ 2,182.78

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ nn 240.00 X

LAD2101-008

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX3266A

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	bol
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	na	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	na	1,600.00	X
To reinstall rear bumper parking sensor.	\$	na	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$	na	170.00	X
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	na	170.00	X
TOTAL	\$		5,100.00	
Over All Total	\$		7,282.78	

(PART-BY-PART) Repair Days

20 Days

1/2 day

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer