



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO21001268/BKvf3e2 Date: 06/04/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBH 7928L	Veh. Inspected	SJL 4230U
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2100287/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/01/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA STREAM	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	RN61083288	Colour	GREY
Odometer	311042 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	FIRENZA	6 mm
L/H Front Tyre	225/45 R17	FIRENZA	6 mm
R/H Rear Tyre	225/45 R17	FIRENZA	6 mm
L/H Rear Tyre	225/45 R17	FIRENZA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/01/2021	Inspection Date	27/01/2021
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	