

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5952J**AAD2101-110***Not Authorized*
1/1 Smp 8340dp

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

26 JAN 2021**SHC5952J**

VF1ABL15AUC281662

RENAULT

LATITUDE

23/01/2021

CHINA

26/06/2015

PART		LIST	
1	1 BUMPER COVER REAR	\$ Bu	561.70 ✓
2	1 BUMPER LOWER REAR	\$ nul/hr	411.90 ✓
3	1 BUMPER BRACKET CTR REAR	\$ S _h	98.10 X
4	1 BUMPER BRACKET SIDE LH REAR	\$ S _h	80.80 X
5	1 BUMPER BRACKET SIDE RH REAR	\$ S _h	82.10 X
6	1 BUMPER RETAINER LH REAR	\$ S _h	54.20 X
7	1 BUMPER RETAINER RH REAR	\$ S _h	59.80 X
8	1 BUMPER BEAM REAR	\$ B _h	547.80 ✓
9	1 BUMPER REFLECTOR LH	\$ S _h	16.60 X
10	1 BOOT REAR	\$ B _h	1,677.20 ✓
11	1 BOOT FINISHER	\$ S _h	344.70 X
12	1 BOOT WEATHERSTRIP	\$ S _h	178.20 X
13	1 BOOT STRUT LH	\$ S _h	145.10 X
14	1 BOOT STRUT RH	\$ S _h	145.10 X
15	1 BOOT HINGE LH	\$ H	254.20 X
16	1 BOOT HINGE RH	\$ H	254.20 X
17	1 BOOT BADGE 'RENAULT'	\$ R _h	82.40 ✓
18	1 BOOT BADGE	\$ R _h	95.80 ✓
TOTAL		\$	5,089.90
10%		\$	508.99
		\$	4,580.91

Special Nett

1	1SET PARKING AID	\$ S _h	700.00 X
2	1SET REAR BUMPER CLIP	\$ R _h	66.00 ✓
3	1SET BUMPER BRACKET CTR CLIP	\$ R _h	33.00 X
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$ R _h	10.00 X
5	1SET BUMPER RETAINER RH CLIP RR	\$ R _h	20.00 X

Trans-cab Auto Services Pte Ltd**AAD2101-110**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5952J

- 6 1SET BUMPER LOWER REAR RIVET
- 7 1SET BUMPER LOWER REAR CLIP
- 8 1 BOOT STICKER TRANSCAB
- 9 1 BOOT STICKER 65553333
- 10 2 WINDSCREEN SEALANT
- 11 1 WINDSCREEN MOULDING
- 12 1 WINDSCREEN INNER SPONGE SEAL

Over All Total	\$	nn	22.00	X
	\$	nn	66.00	✓
(LUMP SUM)	\$	nn	100.00	30sn
Repair Days	\$	nn	100.00	30sn
	\$	nn	150.00	X
	\$	nn	200.00	X
	\$	nn	130.00	X
TOTAL	\$		1,597.00	
TOTAL PARTS	\$		6,177.91	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	440l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	400l
To Rust-Proofing Of The Affected Areas.	\$		170.00	30l
To reinstall rear bumper parking sensor.	\$		170.00	60l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00	60l
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Check Electrical Lighting Concerned.	\$		170.00	15l
TOTAL	\$		7,070.00	

Trans-cab Auto Services Pte Ltd

AAD2101-110

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5952J

Over All Total \$ 17,828.82

(LUMP SUM)

Repair Days

~~20~~ DAYS

3 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: