

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD423Y**AAD2101-112***Not Authorized*
L1 Sing \$5050h

Vehicle No.:
Chassis No.:
Vehicle Make: RENAULT
Vehicle Model: LATITUDE 26 JAN 2021
Date of Accident :
Third Party Insurer : TOKIO
Date of Registration : 09/12/2016

SHD423Y

VF1ABL15AUC283437

RENAULT

LATITUDE

23/01/2021

TOKIO

09/12/2016

PART		LIST
1	1 BUMPER COVER REAR	\$ Btl/cm 561.70 ✓
2	1 BUMPER LOWER REAR	\$ Ndl/cm 411.90 ✓
3	1 BUMPER BRACKET CTR REAR	\$ D11 98.10 ✓
4	1 BUMPER BRACKET SIDE LH REAR	\$ SL 80.80 X
5	1 BUMPER BRACKET SIDE RH REAR	\$ SL 82.10 X
6	1 BUMPER RETAINER LH REAR	\$ SL 54.20 X
7	1 BUMPER RETAINER RH REAR	\$ SL 59.80 X
8	1 BUMPER BEAM REAR	\$ Bg 547.80 ✓
9	1 BUMPER REFLECTOR RH	\$ CM 16.60 ✓
10	1 OUTER PANEL REAR (End Panel)	\$ Bg 745.80 ✓
11	1 OUTER PANEL REAR (End Panel) TRIM	\$ Div 404.56 ✓
12	1 TAILLAMP RH	\$ Mgl/cm 401.40 ✓
13	1 BOOT REAR	\$ Bg 1,677.20 ✓
14	1 BOOT LOCK	\$ N 246.60 X
15	1 BOOT LOCK CATCH	\$ N 41.70 X
16	1 BOOT FINISHER	\$ SL 344.70 X
17	1 BOOT WEATHERSTRIP	\$ Netom 178.20 502m
18	1 BOOT STRUT LH	\$ SL 145.10 X
19	1 BOOT STRUT RH	\$ SL 145.10 X
20	1 BOOT HINGE LH	\$ N 254.20 X
21	1 BOOT HINGE RH	\$ N 254.20 X
22	1 BOOT BADGE 'RENAULT'	\$ MC 82.40 ✓
23	1 BOOT BADGE	\$ MC 95.80 ✓
TOTAL		\$ 6,929.96
10%		\$ 693.00
		\$ 6,236.96

*89.00m***Specical Nett**

Trans-cab Auto Services Pte Ltd

AAD2101-112

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD423Y

1 1SET PARKING AID	\$	700.00 X
2 1SET REAR BUMPER CLIP	\$	66.00 ✓
3 1SET BUMPER BRACKET CTR CLIP	\$	33.00 X
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00 X
5 1SET BUMPER RETAINER RH CLIP RR	\$	20.00 X
6 1SET BUMPER LOWER REAR RIVET	\$	22.00 X
7 1SET BUMPER LOWER REAR CLIP	\$	66.00 ✓
8 1 REAR NUMBER PLATE WITH MOULDING	\$	120.00 X
9 1 BOOT STICKER TRANSCAB	\$	100.00 30sn
10 1 BOOT STICKER 65553333	\$	100.00 30sn
11 2 WINDSCREEN SEALANT	\$	150.00 X
12 1 WINDSCREEN MOULDING	\$	200.00 X
13 1 WINDSCREEN INNER SPONGE SEAL	\$	130.00 X
TOTAL	\$	1,717.00
TOTAL PARTS	\$	7,953.96

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 8601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 6001
To Rust-Proofing Of The Affected Areas.	\$	170.00 601
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 601
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 601
To check steering geometry and computer wheel alignment	\$	220.00 X

Trans-cab Auto Services Pte Ltd

AAD2101-112

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD423Y

To Check Electrical Lighting Concerned.

\$

170.00 20/

TOTAL \$

7,070.00

Over All Total

\$

21,260.93

(LUMP SUM)

Repair Days

20 DAYS

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: