

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 27.01.2021  
Time: 10:35:55  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305450591  
REGN NO : SHA2990D  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 26.06.2019  
DATE/TIME IN : 26.01.2021 16:10  
ACCIDENT DATE : 26.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

|                        |                           |      |        |       |        |                    |
|------------------------|---------------------------|------|--------|-------|--------|--------------------|
| 0001 FNPS              | NO PLATE(S) WITH TRIM COV | 1 N  | 55.00  | 0.00  | 55.00  | — CBA              |
| 0002 04-01-0104-2282-G | COVER-RR BUMPER#          | 1 L  | 459.40 | 20.00 | 367.52 | x Repair           |
| 0003 04-01-0101-0111-G | BUMPER COVER CLIP REAR    | 10 L | 22.00  | 20.00 | 17.60  | <del>10</del> x NN |
| 0004 04-01-0104-2533-G | MOULDING ASSY-RR BUMPER C | 1 L  | 451.25 | 20.00 | 361.00 | / Re               |
| 0005 04-01-0104-1150-A | PROTECTOR MAT             | 1 N  | 50.00  | 2.00- | 50.00  | x NN               |

SUB-TOTAL : 851.12

JOB NATURE

|             |                             |        |     |
|-------------|-----------------------------|--------|-----|
| 0000 L      | PANEL BEATING               | 400.00 | 350 |
| 0001 23-502 | SPRAYPAINT ON AFFECTED AREA | 300.00 | 250 |
| 0002 20-22  | REMOVE/REFIX REVERSE SENSOR | 80.00  | 40  |

SUB-TOTAL : 780.00

2 Days.  
P/P  
before paint photos.  
After paint photos.  
Gino Giam  
27/1/2021

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: