

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21001274/UVF3E2

Date: 09/02/2021

REFERENCE

Insured/Claimant: YEK YU HING Policy No: DMPCSNW00124562002

Date of Loss: 24/01/2021 Nature of Claim: OD

Claim No: SNM21D200448/C01/SJT3680T/TANK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT3680T**

Make & Model: TOYOTA VIOS, 1.5 (A)

Engine No: 1NZX974787

Reg. Date: 06/10/2009 (Man. Year: 2009)

Chassis No: MR053HY9305131516

Colour: Red

Odometer: 148545 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Goodyear 5 mm

Rear Left Side: Goodyear 7 mm

Front Right Side: Goodyear 5 mm

Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	500.00	-500.00	
Nett Amount (S\$)	0.00	-500.00	500.00	

INSPECTION

Date of Assignment:	27/01/2021	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	27/01/2021	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	0.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$18,000.00
OMV :	\$12,717.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$14,743.00
COE Rebate (2) :	\$10,836.00
Total Rebate (1) + (2) = :	\$10,836.00

The total amount incurred will be Market Value \$18,000.00 minus Total Rebate \$10,836.00 = \$7,164.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Feb 2021)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT3680T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >