



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SM AUTOMOTIVE 1 KAKI BUKIT AVENUE 6 BLOCK D AUTOBAY #01-43 SINGAPORE 417883 ON BEHALF OF KOH JOO HONG MICHAEL			Ref: CS/TP21001279/Aqd3e2 Date: 03/03/2021 Code: TP440	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SKP 2085C	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	25/01/2021	
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 316I	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WBA3A12080J722112	Colour	WHITE
	Odometer	120371 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	GOODYEAR	6 mm
	L/H Front Tyre	225/45 R18	GOODYEAR	6 mm
	R/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
	L/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/01/2021	Inspection Date	25/01/2021
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	