

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

25/01/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 25/01/2021

Supplementary repair cost for vehicle no: SKP2085C BMW 316I 1.6 AT HID 14'

CHASSIS: WBA3A12080J722112

S/n	Qty	Items	U/price	Amount
1	1	Front Support Panel Garnish Top <i>cracked</i>		\$238.60 ✓ 185
2	1	Front Support Panel Garnish Btm <i>cracked</i>		\$324.50 ✓ 215
3	1	Front Bumper Reinforcement Lower <i>Bent</i>		\$366.20 ✓ 185
4	1	Rear Bumper Reinforcement Cover <i>cracked</i>		\$189.80 ✓

Total:- \$1,119.10

774.80

Supplementary: 688.56.2