

Accident Repair Estimate

Accident Date:

Bus Registration Number:SBS6572C

Accident Time:

Bus Type:MAN A22

Accident Report Number E 0382021

Date of Survey:

3rd Party Claim against:

Section A

Parts and Material Cost			
Parts or Item Description	Price	Quantity	Total Cost
REAR BUMPER W /RR FOGLAMP OS	\$364.00	CRA ✓ 1	\$ 364.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
		Total Parts & Material Cost	\$ 364.00

Section B

Assessment/Repair/Spray paint (labour Cost)		
Contractor Labour Cost	\$	450.00
Workshop Admin Cost	\$	192.00
Livery/Advertisement Cost		
Towing Cost	\$	-
	Total Labour Cost	\$ 642.00

Section C

Summary		
Total Cost	\$	1,006.00

CHONG YONG GUANG
TECHNICAL OFFICER
SELETAR BUS WORKSHOP