



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2104601

INV Date 01/07/2021

Reference CS/EQI21001288/T1tf3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SBS 6572C
Insured Veh. GBH 7860Y
Claim No. DM21HO00011/SG
Policy No. DMCPHQ20-000354
Accident Date 29/12/2020
Inspection Date 27/01/2021

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Ref: CS/EQI21001288/T1f3e2

Date: 01/07/2021

Code: EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 7860Y	Veh. Inspected	SBS 6572C
Policy No.	DMCPHQ20-000354	Coverage (\$)	0.00
Claim No.	DM21HO00011/SG	Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	27/01/2021

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CITARO	c.c	6374
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WEB62808323128614	Colour	GREEN
Odometer	403310 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/12/2020	Inspection Date	27/01/2021
Survey held at	3 Yio Chu Kang Crescent road		
Repairer	SBS TRANSIT LTD (HQ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **1 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 6572C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BLINKER LAMP; FRT LEFT	CUT	43.00	43.00
1	BUMPERETTE;FRT BUMPERETTE.N/S	CRACKED	536.00	536.00
			579.00	579.00
LABOUR				
	(2) WORKSHOP LABOUR.	NOT NECESSARY	192.00	-
	CONTRACTOR'S REPAIR CHARGES.		400.00	400.00
			592.00	400.00
GRAND TOTAL			1,171.00	979.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				979.00

Report Ref No. CS/EQI21001288/T1tf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 06/01/2021 13:52 (SGT)
Date of Accident 29/12/2020 13:35 (SGT)
Exact Location of Accident Opp Zhongshan Mall, Singapore
Additional Location Information BALESTIER ROAD NEAR SINGAPORE KHALSA ASSOCIATION
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SBS6572C

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner SBS TRANSIT LTD
Company Reg No 1XXXXXXXXXXTE01
Email Address thammk@sbstransit.com.sg
Mobile Phone No (Phone) +65-63754198
Alternative Phone No (Office) +65-63754198

VEHICLE PARTICULARS

Manufacturer Mercedes
Model Citaro
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Bus

INSURANCE COMPANY

Name of Insurance Company First Capital
Type of Coverage ActLiability
Fleet Policy No
Policy Number D-20095429MFBP
Cover Note Number -

DRIVER

Name of Driver Silveraju A/L Suppayah
Passport No/FIN FXXXX829X
Date Of Birth 09/01/1967
Occupation Outdoor

Date Of Driving Pass	07/02/1994
Driving experience	26 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-82495896
Alt. Phone Number	-
Email Address	thammk@sbstransit.com.sg
Address	40065 Jalan Banjaran 5 Kempas Postal Code : 81200
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	12
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Male

PASSENGER 2

Name	UNKNOWN
Gender	Female

PASSENGER 3

Name	UNKNOWN
Gender	Male

PASSENGER 4

Name	UNKNOWN
Gender	Female

PASSENGER 5

Name	UNKNOWN
Gender	Male

PASSENGER 6

Name	UNKNOWN
Gender	Female

PASSENGER 7

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
--	-----

Police Station Name	Ang Mo Kio South Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18004519999
Alt. Police Station Phone No	(Fax) +65-65535679
Police Station Address	81 Ang Mo Kio Ave 3 Singapore 569929
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I was driving along Balestier road just before the bus stop outside the Singapore Indian Association. I drove on the 1st lane to go straight to Whampoa at the next bus stop as the 2nd and 3rd lane were congested. On the 2nd lane, another van (GBH7860Y) suddenly changed into my lane. I could not brake on time and collided onto the driver side of the van. My bus had some minor scratches while the van also had scratches. No one was injured. We exchanged particulars after both of us parked at the next bus stop. However, one of my passenger (Mirna, h/p : 96279540, 83 whampoa drive, #08-294) complained that her son knocked onto a pole inside the bus. She informed that her son was fine and did not need to see doctor. I also had a witness that saw that the van cut into my lane which resulted in the accident. (Witness : Imansyah Budiman, h/p : 97556327). That 's all.

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH7860Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Goods vehicle
Name of Driver	Razeki Bin Awang @ Mohamad Edk
Contact Number	(Phone) +65-84145245
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	RIGHT FRONT DMG
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	Mirna (83 whampoa drive, #08-294) 's son.
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	knocked onto pole
Injured person in which vehicle?	SBS6572C
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

WITNESS DETAILS

WITNESS 1

Name	Imansyah Budiman
Phone	(Phone) +65-97556327
Email	-



**SINGAPORE
POLICE FORCE**



F/20201229/2047

1 of 2

POLICE REPORT (NP299)

Report No. F/20201229/2047

Police Station Of Origin
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999


Date/Time Report Made 29/12/2020 15:34	Vide Report No.	Station Diary No. 92
Name Of Informant SILVERAJU SUPPAYAH	Address APT BLK 163 ANG MO KIO AVENUE 4 #04-476 MAYFLOWER SHOPPING & FOOD CENT SINGAPORE 560163	
ID Type / ID No. FIN NO / F7475829X	Contact No. Home/Office	Mobile 82495896
Nationality MALAYSIAN	Email Address	
Occupation Bus Driver	Sex Male	Age 53
Institution/School Name	Date of Birth 09/01/1967	Race Indian
Date/Time Of Incident 29/12/2020 13:40	Location Of Incident BALESTIER ROAD SINGAPORE	

Brief details.

On 29/12/2020, at about 1.40pm, I was driving my bus (SBS6572C) along Balestier road, just before the bus stop outside Singapore Indian Association, I drove on the 3rd lane to go straight to Whampoa at the next bus stop as the 1st and 2nd lane were congested. On the 2nd lane, another vehicle, GBH7860Y, (Razeki Bin Awang @ Mohamad Edkhan Bin Sohani, S7036291J, HP: 84145245) suddenly changed lane into my lane. I could not brake my bus on time, and collided onto the driver side of the vehicle. My bus had some minor scratches while the other vehicle also had scratches. No one was injured. We

Signature Of Officer Recording The Report: F / Sgt 2 KOH WEI JUN, JONES <i>Ju</i>	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 29/12/2020 15:34
Officer In-Charge Of Case: F / Ang Mo Kio South N.P.C / Sr Staff Sgt MUHAMMAD RAIMI BIN MIS NAM Contact No.: 65536745	Classification Of Case:

Authentication Stamp





**SINGAPORE
POLICE FORCE**



F/20201229/2047

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20201229/2047

exchanged particulars after both of us parked at the next bus stop. However, one of my passenger (Mirna, HP: 96279540, 83 Whampoa Drive #08-294) complained that her son knocked onto a pole inside my bus. She informed that her son is fine and does not need to see a doctor. I also have a witness that saw that the van cut into my lane which resulted in the accident. (Witness: Imansyah Budiman, HP: 97556327)

I am lodging this police report for my company record purposes.

Signature Of Officer Recording The Report: F / Sgt 2 KOH WEI JUN, JONES <i>Ju</i>	Signature Of Informant: <i>ST</i>
Signature Of Interpreter: Not applicable	Date/Time: 29/12/2020 15:34
Officer In-Charge Of Case: F / Ang Mo Kio South N.P.C / Sr Staff Sgt MUHAMMAD RAIMI BIN MIS NAM Contact No.: 65536745	Classification Of Case:

Authentication Stamp

SN 085

Ju Signature: _____
Singapore Police Force



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBS 6572C

INSPECTION








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBS 6572C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBS 6572C

RE-INSPECTION

