

Certification for Bus Repairs



CBR REF NO. : SE20210383

Depot : SE Report No.: E53992020 BUS VEHICLE NO. : SBS6572C
 Driver's Co no. & Name : 13497 Silveraju A/L Suppavah
 Accident Date : 29/12/2020

Date in : 26/01/2021 Date Out : 28/01/2021

Yr Of Reg	Make / Model	Chassis No.
2015	MB Citaro O530, SD, AC, 2 Axle	WEB62808323128614

Stock Code	Description	Quantity	Total Material cost (S\$)
30600025	BLINKER LAMP;FRT LEFT	1	\$43.00
30600386	BUMPERETTE;FRT BUMPERETTE.N/S	1	\$536.00
TOTAL FOR PARTS			S\$ 579.00
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	S\$	192.00
2	Contractor's repair charges	S\$	400.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			S\$ 592.00
Repair cost of Advertisement / Livery			S\$ -
TOTAL DAMAGE			S\$ 1171.00

ent ✓
car ✓
X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Certification for Bus Repairs



CBR REF NO. : SE20210383

Depot : SE Report No.: E53992020 BUS VEHICLE NO. : SBS6572C
 Driver's Co no. & Name : 13497 Silveraju A/L Suppavah
 Accident Date : 29/12/2020

Date in : 26/01/2021 Date Out : 28/01/2021

Yr Of Reg	Make / Model	Chassis No.		
2015	MB Citaro O530, SD, AC, 2 Axle	WEB62808323128614		
TOTAL DAMAGE			S\$	1171.00
Overheads			S\$	351.30
Towing Charges			S\$	-
Loss of Use			S\$	356.29
TOTAL LOSS			S\$	1878.59

Prepared By : Chong Yong Guang

Date : 29/01/2021

Approved By
Workshop Mgr : Zee Chee Wah

Date : 01/02/2021

	Survey Fee	refer to Group Claims
TOTAL DUE	S\$	1878.59

Acknowledged By
Depot Safety : Tham Meng Khuan

Date : 02/02/2021

* This is computer generated document and does not require signature