

Am 1289 (Agg3

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

TP AXA

Vehicle Number : SLH8303P
Vehicle Model : HONDA VEZEL
Accident Date : 16.01.2021
Original Reg Date : 21.11.2016

Date : 02.02.2021
Chassis : RU11208491
TP Ins. INDIA

Cecilia

ESTIMATE

1	1 pc	Front Bumper <i>dent</i>		958.00	80
2	2 pcs	Front Bumper Side Retainers <i>RH LH</i>	68.90	137.80	35
4	1 pc	Front Bumper Reinforcement <i>3rd</i>		365.00	+
5	2 pcs	Front Bumper Reinforcement Top Garnish <i>2nd</i>	62.00	124.00	+
6	1 pc	Front Bumper Lower Grille <i>new</i>		189.00	+
7	1 pc	Front Bumper Fog Lamp RH <i>new</i>		359.00	+
8	1 pc	Front Bumper Fog Lamps Cover RH <i>new</i>		69.20	+
9	1 pc	Front Bumper Lower Skirt <i>at</i>		550.00	351
10	1 pc	Front Grille <i>2</i>		350.00	+
11	1 pc	Front Center Grille <i>1st</i>		186.00	+
12	1 pc	Front Grille Badge <i>1st</i>		56.00	+
13	1 set	Front Grille Clips <i>1st</i>		30.00	+
14	1 pc	Front Fender RH <i>Dented</i>		591.00	✓
15	1 pc	Front Fender inner cowling RH <i>new torn</i>		189.60	✓
16	1 pc	Front Fender Arch Garnish RH <i>1st</i>		285.90	185
18	1 pc	Headlamp RH (HID) <i>cracked</i>		1,859.40	✓
19	1 pc	Headlamps Side Garnish RH <i>new</i>		75.00	+
20	1 pc	Headlamps Bottom Retainer RH <i>new</i>		85.60	+
21	1set	Headlamps Clips <i>new</i>		30.00	10
22	1 pc	Front Absorber RH <i>new</i>		530.00	x.
23	1 pc	Front Lower Arm RH <i>Best</i>		398.70	✓
24	1 pc	Front Knuckle Arm RH <i>new</i>		429.10	+
25	1 pc	Front Wheel hub Bearing RH <i>Dented</i>		345.80	✓

8,194.70

Less 20% 1,638.94

6,555.76

4855.50

3884.40

國際汽車維修
KT MOTORWERK
 Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
 (Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
 Email: ktmotorwerk@hotmail.com
 Reg. No. 533734628

Special Nett

1	1 pc	Front bumper lower chrome garnish(accessories)		350.00	180
2	1 pc	Front Sport Rim RH		850.00	400
3	1 set	Front bumper clips		30.00	—
4	1 set	Front fender inner cowling clips		30.00	—
5	1 set	Front bumper lower skirt clips		30.00	—
			670	total	1,290.00

Labour charge

Panel Beating		1,200.00	500
Spray painting		1,200.00	400
Check Wiring on front headlamps and settling		120.00	30
Remove and install front undercarriage.		180.00	150
To perform computerize wheel alignment.		120.00	80
		total	\$ 2,820.00

Grand total	10,665.76
--------------------	------------------

Adrian Lj
 I/S 02/02/21

05 Days.

total: 571440

I/S: A.S.K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: