



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Pek Kok How (Bai Guohao) 442 Sin Ming Avenue #12-423 Singapore 570442 Mobile: 94771022			
			Document No. 0					
			Document Date 26/01/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ASU60R	ANTGT L1	23/09/2019	SMQ0265J	0	20667	67/DS/SMQ0265J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH30J004274		8ARZ151267	60	Sam San Joi	26/01/2021 13.00		--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBH8108E ACC DATE:25/01/2021 DRIVE IN:26/01/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:						30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON LH REAR ACCIDENT AREAS						183.18
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR						180.00
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST						180.00
5	S	BP-SUBLET TO RESET ECU AND REPROGRAMME						180.00
6	B	BP-LAB2 REPLACE LH REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN LH REAR ACCIDENT AFFECTED AREAS						1440.00
7	B	BP-RES2 RESPRAY JOB ON LH REAR ACCIDENT AFFECTED AREAS						1770.00
8	1	T52159-48933	COVER, RR BUMPER		1.00	904.00		904.00
9	2	T52156-48050	SUPPORT, RR BUMPER		1.00	82.70		82.70
10	3	S52161-0K040	CLIPS		10.00	4.10		41.00
11	4	T89348-58120	RETAINER, ULTRASONIC		4.00	16.00		64.00
12	5	T61602-48030	PANEL SUB-ASSY,		1.00	1531.10		1531.10
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 6,585.98	
					Parts 2,622.80		GST 7.00% 461.02	
					Labour 3,600.00			
					Sublet 363.18		Less 0.00	
					Lubrication/Fluid 0.00			
					Others 0.00		Amount Due 7,047.00	

Customer Copy