



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details		Account No.	Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Pek Kok How (Bai Guohao)				
		Document No. 39011574	442 Sin Ming Avenue #12-423 Singapore 570442				
		Document Date 29/03/2021	Mobile: 94771022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	23/09/2019	SMQ0265J	27267	20667	67/DS/SMQ0265J
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEKB3GH30J004274		8ARZ151267	60	Sam San Joi	26/01/2021 13.32		29/03/2021 16.07
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBH8108E ACC DATE:25/01/2021 DRIVE IN:26/01/2021 DATE-IN:22/02/2021 DATE SURVEY:22/02/2021 NO OF REPAIR DAYS:4 DAYS BY:ADRIAN(LKK)				20.00	
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON LH REAR ACCIDENT AREAS	0619			183.18	
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR	*			180.00	
4	B	BP-LAB2 REPLACE LH REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN LH REAR ACCIDENT AFFECTED AREAS	*			1080.00	
5	B	BP-RES2 RESPRAY JOB ON LH REAR ACCIDENT AFFECTED AREAS	*			1180.00	
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	BP59			180.00	
7	1	T52159-48933 COVER, RR BUMPER	1.00	904.00		904.00	
8	2	S52161-0K040 PIECE, RR BUMPER	10.00	4.10		41.00	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd					3,768.18		
		Please acknowledge receipt of vehicle			GST 7.00%		
					263.77		
					Less		
					0.00		
					Amount Due		
					4,031.95		

Customer Copy