

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6475 2112 FAX: 6475 4666
WEBSITE: <http://www.ricardo.com.sg>



QUOTATION

M/S : LIM FANG YONG MARK

19 SENNETT PLACE
SINGAPORE 466854

H/P: 98788429

NO: WQT0801134

DATE: 26 Jan 2021

A/C CODE: C016495

YOUR REF: SLG7494H

VEH REG NO: SLG7494H

MAKE/MODEL: VOLVO S60 T2 A/T

SALESMAN:

PAGE:1

Description	Quantity	Unit Price	%	Amount
		S\$		S\$
WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE. DOA: 25/01/2021 ACCIDENT INVOLVING: SLG7494H, SLN2544T, SLQ4494P & SMP8937G CLAIM TYPE: 3RD PARTY CLAIM AGAINST SLN2544T (INSURED WITH AIG)				
1 REAR BUMPER	1 PC	1,922.80		1,922.80
2 REAR BUMPER SPOILER - UPPER	1 PC	618.20		618.20
3 REAR BUMPER SPOILER - LOWER	1 PC	512.60		512.60
4 REAR BUMPER CENTER RETAINER	1 PC	107.80		107.80
5 REAR BUMPER SIDE RETAINER LH & RH	4 PC	71.50		286.00
6 REAR BUMPER REINFORCEMENT	1 PC	1,544.40		1,544.40
7 REAR BUMPER CLIPS	10 PC	8.00		80.00
8 TO CUT, WELD & STRAIGHTEN REAR PORTION OF CAR CAUSED BY ACCIDENT, ADJUST & REPLACE DAMAGE PARTS.	1 SVC	500.00		500.00
9 TO SPRAY PAINT ON REPAIRED AREA.	1 SVC	500.00		500.00
10 TO PROGRAM REAR SENSOR SETTING	1 SVC	450.00		450.00
Total				S\$ 6,521.80
Add GST @ 7%				456.53
Grand Total				<u>S\$ 6,978.33</u>

TOTAL: SINGAPORE DOLLAR SIX THOUSAND NINE HUNDRED SEVENTY EIGHT AND CENTS THIRTY THREE ONLY

LIM FANG YONG MARK

For RICARDO AUTO CENTRE PTE LTD

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE