

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883
Email: admin@cnmotorspl.com
Tel: 6509 5545 Fax: 6509 5567
UEN: 202026492W

12/01/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Chinn.
Jaslin

Accident date: 12/01/2021

Estimated repair cost for vehicle no: SJS2540B TOYOTA PREMIO 1.5F A 09'

CHASSIS: NZT2603036857

S/n	Qty	Items	U/price	Amount
1	1	Rear Bootlid <i>Repair</i>		\$1,189.50 <i>x</i>
2	1	Rear Bootlid R/H Side Reflector <i>Not in</i>		\$285.00 <i>x</i>
3	1	Rear Bootlid Premio Logo <i>2</i>		\$64.00 <i>✓</i>
4	1	Rear Bootlid Emblem Logo <i>✓</i>		\$58.00 <i>✓</i>
5	1	Rear Bootlid P Logo <i>✓</i>		\$35.00 <i>✓</i>
6	1	Rear R/H Tail Lamp <i>Not in</i>		\$480.10 <i>x</i>
7	1	Rear Bumper <i>Debond</i>		\$1,189.50 <i>968</i>
8	8	Rear Bumper Clip <i>Not in</i>	\$6.50	\$52.00 <i>30</i>
9	1	Rear Bumper Reverse Sensor <i>Domaged</i>		\$380.00 <i>200 (SW)</i>
10	2	Rear Bumper Side Retainer <i>Not in</i>	\$89.50	\$179.00 <i>110</i>
11	1	Rear R/H Fender Inner Trim Board <i>Not in</i>		\$324.50 <i>x</i>
12	1	Rear End Panel <i>Repair</i>		\$561.00 <i>x</i>
13	1	Rear End Panel Top Garnish <i>Debond</i>		\$371.00 <i>281</i>

Subtotal :- \$5,168.60

Labour charges

To remove & refit cushion

~~\$280.00~~ *40*

To remove & refit rear camera

~~\$180.00~~ *x*

To check wiring

~~\$100.00~~ *30*

Tuff kote

~~\$150.00~~ *50*

Panel beating

~~\$600.00~~ *250*

Spray painting

~~\$600.00~~ *400*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$1,910.00

Total:- \$7,078.60

1.7K

total: 2129.50

HS: 1.7K

04 Days