

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21001318/QBA3Q2

Date: 05/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	D20MFL0000326_01
Claimant		
Vehicle No : SGM2721M	Insured Vehicle No :	SLL9016R
Date of Loss: 21/01/2021	Nature of Claim: TP	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM2721M	Engine No:	G4EE6H038288
Make & Model:	KIA RIO, 1.4 HB (M)	Chassis No:	KNADE241266118027
Reg. Date:	13/10/2006 (Man. Year: 2006)	Odometer:	140577 km
Colour:	Orange		
Engine Capacity:	1399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,700.00	724.00	976.00	57.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,040.00	400.00	640.00	61.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,740.00	1,124.00	1,616.00	58.98
Approved Total (Overridden) (S\$)		900.00		
(S\$)	2,740.00	900.00	1,840.00	67.15
+ GST 7.00/7.00% (S\$)	191.80	63.00	128.80	67.15
Nett Amount (S\$)	2,931.80	963.00	1,968.80	67.15
+ Car Rental (2.0 x S\$120.00/day + 7.00% GST) (S\$)		256.80		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,227.25		
Global Sum Settlement (S\$)		1,180.00		

INSPECTION

Date of Assignment:	27/01/2021	
Date Inspected:	01/02/2021 Inspected At:	Automotive Repair Centre Pte Ltd (HQ)
		38 Woodlands Industrial Park E1, #05-18
		Singapore 757700

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2021)
Parts:	143	KIA RIO 1.4 HB (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM2721M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	480.00 F	*480.00 FL
2	1		*REAR BUMPER TOP BLACK PROTECTOR	Deformed	120.00 F	*120.00 FL
3	10		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
4	1		*REAR BUMPER RETAINER RH	Broken	25.00 F	*25.00 FL
5	1		*REAR BUMPER RETAINER LH	Serviceable	25.00 F	*- FL
6	1		*REAR REINFORCEMENT	Serviceable	160.00 F	*- FL
7	1		*REAR SPONGE	Serviceable	120.00 F	*- FL
8	1		*END PANEL	Serviceable	340.00 F	*- FL
9	2		*REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS
					Sub Total (\$\$)	1,700.00 855.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 131.00
					Total Parts (\$\$)	1,700.00 724.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING (REAR BUMPER & REAR FENDER RH)	New	440.00	200.00
2	REMOVE AND REFIT FRONT & REAR AFFECTED AREA & REAR END PANEL	New	600.00	200.00
Gross Labour Cost (S\$)			1,040.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >