

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2101-017
DATE : 25-Jan-2021
POLICY NO. : AVIVA 10438077
VEHICLE REG. NO. : SGM2721M
VEHICLE MAKE : KIA RIO 1.4M HB**TO** Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street, #04-#05 IOB Building
Singapore 049711
Tel: 6347 6100 Fax: 6224 4174 / 6225 7743**FOR SURVEYOR****ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 480.00	\$ 480.00
2	Rear Bumper Top Black Protector	1	\$ 120.00	\$ 120.00
3	Rear Bumper Clips	10	\$ 3.00	\$ 30.00
4	Rear Bumper Retainer RH	1	\$ 25.00	\$ 25.00
5	Rear Bumper Retainer LH	1	\$ 25.00	\$ 25.00
6	Rear Reinforcement	1	\$ 160.00	\$ 160.00
7	Rear Sponge	1	\$ 120.00	\$ 120.00
8	End Panel	1	\$ 340.00	\$ 340.00
Total Spare Parts				\$ 1,300.00
	<u>SPECIAL NETT</u>			
9	Reverse Sensor	2	\$ 200.00	\$ 400.00
Total Special Nett				\$ 400.00
	<u>LABOUR</u>			
10	Spray Painting (Rear Bumper & Rear Fender RH)	1	\$ 440.00	\$ 440.00
11	Remove and Refit Front & Rear Affected Area & Rear End Panel	1	\$ 600.00	\$ 600.00
Total Labour				\$ 1,040.00
Amount Before Excess				\$ 2,740.00
Add GST @ 7%				191.80
Total Amount Payable				\$ 2,931.80

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.