

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21001322/T1GS3Q2
Date: 03/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993686
Claimant Vehicle No :	SLC2244S	Insured Vehicle No :	SLQ9901J
Date of Loss:	26/01/2021	Nature of Claim:	TP
		Claim No:	4260351163SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC2244S		
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK083131
Reg. Date:	18/11/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF48KA080282
Colour:	Black	Odometer:	14998 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,408.00	376.80	6,031.20	94.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,910.00	1,978.80	6,931.20	77.79
+ GST 7.00/7.00% (S\$)	623.70	138.52	485.18	77.79

Nett Amount (S\$)	9,533.70	2,117.32	7,416.38	77.79
+ Car Rental (3.0 x S\$150.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,574.77		

INSPECTION

Date of Assignment: 29/01/2021

Date Inspected: 29/01/2021

Estimated Period of Repair: 3.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,996.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	459.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	223.00 FS	*178.00 FS
4	1		*REAR BUMPER SPOILER	Cut	249.00 FS	*198.80 FS
5	1		*REAR BUMPER TRIM	Not Necessary	292.00 FS	*- FS
6	1		*REAR BUMPER BRACKET LH	Not Necessary	116.00 FS	*- FS
7	1		*REAR LIGHT REFLECTOR LH	Not Necessary	41.00 FS	*- FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,063.00 FS	*- FS
9	2		*REAR BUMPER REINFORCEMENT BEAM SEAL	Not Necessary	28.00 FS	*- FS
10	2		*REAR BUMPER GUIDE SECTION LH/RH	Not Necessary	46.00 FS	*- FS
11	1		*REAR BUMPER HOLDING STRAP	Not Necessary	83.00 FS	*- FS
12	1		*REAR AERIAL RETAINER	Not Necessary	26.00 FS	*- FS
13	1		*REAR BUMPER PARKING AND AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
14	1		*REAR BUMPER PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
15	1		*REAR BUMPER EXHAUST TRIM LH	Not Necessary	354.00 FS	*- FS
16	1		*TELEPHONE AERIAL	Not Necessary	174.00 FS	*- FS
17	1		*REAR BUMPER GUIDE SECTION LH	Not Necessary	44.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)**6,408.00****376.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .REORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >