

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0094/2021/KS
DATE : 28-Jan-21
WIP : 13364

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SLC 2244 S

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR CENDANA CARMELO CODERES
ADDRESS : 11 ELIAS GREEN
#05-05
SINGAPORE 519964
TELEPHONE : HP +65 96322764
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900248258-01
VEHICLE NO : **SLC 2244 S**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 18/11/2019
ENGINE NO : CVK 083131
CHASSIS NO : WAUZZZF48KA080282
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jan-21
PLACE OF ACCIDENT : 1 ELIAS GREEN, SINGAPORE 519959
RESIDENCE CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLC 2244 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	
3	TO DISMANTLE AND RENEW REAR BUMPER . RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	
4	TO RESPRAY REAR BUMPER.	\$ 900.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 2,502.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 2244 S

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER		\$	2,996.00	
2	REAR BUMPER FIXINGS PARTS		\$	459.00	
3	REAR BUMPER SECURING STRIP		\$	223.00	
4	REAR BUMPER SPOILER		\$	249.00	
5	REAR BUMPER TRIM		\$	292.00	
6	REAR BUMPER BRACKET LH		\$	116.00	
7	REAR LIGHT REFLECTOR LH		\$	41.00	
8	REAR BUMPER REINFORCEMENT BEAM		\$	1,063.00	
9	REAR BUMPER REINFORCEMENT BEAM SEAL	2	\$	28.00	
10	REAR BUMPER GUIDE SECTION LH / RH	2	\$	46.00	
11	REAR BUMPER HOLDING STRAP		\$	83.00	
12	REAR AERIAL RETAINER		\$	26.00	
13	REAR BUMPER PARKING AID SENSOR			TBC	
14	REAR BUMPER PARKING AID SENSOR SEAL RING		\$	14.00	
15	REAR BUMPER EXHAUST TRIM LH		\$	354.00	
16	TELEPHONE AERIAL		\$	174.00	
17	REAR BUMPER GUIDE SECTION LH		\$	44.00	
18	SUNDRIES		\$	200.00	
TOTAL SPARE PARTS		:	\$	6,408.00	
TOTAL LABOUR CHARGES		:	\$	2,502.00	
GRAND TOTAL		:	\$	8,910.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT