

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SHQ6601H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CRP	CONDUCT CONSULT, RESET & PROGRAMMING	240.00	/
2	PDVR	SUPPLY & INSTALL PAPAGO GS360DVR MB	357.00	/
3	PSC	PULL/STRAIGHTEN CHASSIS	350.00	? XN
4	RIBH	REMOVE/INSTALL BLOWER & HEATER UNIT TO FACILITATES REPAIRS	240.00	? /
5	RIEMA	REMOVE/INSTALL EXHAUST MUFFLER ASSY	240.00	? XN
6	RISCC	REMOVE/INSTALL SEAT & CUSHION CARPET	240.00	? /
7	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	/
8	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 05	600.00	120 /
9	RRWIRE	REMOVE/REPAIR WIRE HARDNESS (REVERSE SENSOR)	240.00	? XN
10	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	/
11	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 05	500.00	100 /
12	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	/
13	UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	/
14	ZZ/001	REPAIR LH/RH REAR FENDER AND RENEAR TAILGATE (TOP/BOTTOM), END PANEL, S/TYRE HOUSING, REAR BUMPER @390	3900.00	1950 + 390 = 2340 /
15	ZZ/002	S/PAINT REAR PORTION, CHASIS FRAME, S/TYRE HOUSING AND LH/RH REAR PILLAR @250	3050.00	1520 + 250 = 1750 /
16	ZZ/003	R/I REAR WHEELHOUSE FINISHER, PILLAR FINISHER TO ASSIST REPAIR	240.00	? /
17	ZZ/004	DISCONNECT/CONNET POWER SUPPLY	240.00	/
18	ZZ/005	SUPPLY AND RENEW REAR NO PLATE (SMART PLATE WITH CASING) LONG		
19	ZZ/006	CHECK LIGHTING	48.00	/
20	ZZ/007	VACUUM LOOSE GLASS (REAR WINDSCREEN)	240.00	/
21	ZZ/008	(REPAIR LH/RH REAR PILLAR)		

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
22	ZZ/009	TRANSFER REAR TAIL MECHNICAL PARTS OR RENEW (TOP/BOTTOM)	240.00	
TOTAL LABOUR CHARGES			11535.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 HANDLE-PULL TAILGATE <i>de ✓</i>	90940-4N000	19.60 ✓		
2 LICENSE PLATE LAMP \$80.20 EA X 02 ? <i>XSVL</i>	26510-8990E	160.40 X		
3 REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG RLP <i>ba ✓</i>				50.00 ✓
4 MUFFLER ASSY ? <i>XSVL</i>	20350-5TL0B			828.00 X
5 GASKET-EXHAUST ? <i>XAN</i>	20691-19B0A			4.40 X
6 MOUNTING EXHAUST ? <i>XAN</i>	20651-CY00B			21.80 X
7 MOUNTING EXHAUST ? <i>XAN</i>	20651-4N000			11.20 X
8 HARNESS-CORNER SENSOR REVERSE ? <i>XSVL</i>	24093-5TT0B	194.40 X		
9 SENSOR ASSY REAR BUMPER (OUTER) \$232.00 EA X 02 ? <i>XSVL</i>	28438-5TT1C			464.00 X
10 COVER REAR BUMPER SENSOR (OUTER) \$96.30 EA X 02 ? <i>XSVL</i>	28533-5TT1D			192.60 X
11 SENSOR BUMPER CENTER \$232.00 EA X 02 <i>ne ✓</i>	28438-5TT1B			464.00 ✓
12 COVER REAR BUMPER CENTER SENSOR \$72.50 EA X 02 <i>ne ✓</i>	28533-5ZA0A			145.00 ✓
13 LAMP COMB RR,LH ? <i>XSVL</i>	26555-5TT0A	560.30 X		
14 LAMP COMB RR,RH <i>ca ✓</i>	26550-5TT0A	560.30 ✓		
15 GROMET TAILGATE \$4.90 EA X 02 <i>ne ✓</i>	26557-2U001	9.80 ✓		
16 GROMET TAILGATE \$4.90 EA X 02 <i>ne ✓</i>	26557-2U000	9.80 ✓		
17 LAMP ASSY-STOP 3RD <i>XSVL</i>	26590-5TA0A			237.50 X
18 CAMERA ASSY ALL VIEW (REAR) ? <i>SVL X</i>	28442-5TA3A	750.00 X		
19 ARM ASSY-RR WIPER ? <i>SVL X</i>	28780-5AL0A			59.40 X
20 REFILL-RR WIPER ? <i>SVL X</i>	28795-5AA0A			12.50 X
21 COVER-ARM, BACK WIPER ? <i>SVL X</i>	28782-5AA0A			11.20 X
22 MOTOR-WIPER ? <i>XSVL</i>	28710-5TA0B			479.70 X
23 END PANEL TOP <i>bt ✓</i>	75610-5TA0A			242.50 ✓
24 INSULATOR HEAT S/TYRE HOUSING ? <i>regul ✓</i>	G5930-89904	132.10 X		
25 PROTECTOR-LH REAR FENDER <i>XSVL</i>	76749-5TF0A	117.70 X		

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 PROTECTOR-RH FENER REAR <i>X SVC</i>	76748-5TF0A	117.70	X	
27 CLIP FENDER \$1.30 EA X 06 <i>re ✓</i>	01553-05131	7.80	/	
28 DRAFTER-AIR LH REAR <i>2 X SVC</i>	76804-5TA1A	67.40	X	
29 VALVE LH REAR FENDER \$4.90 EA X 02 <i>X SVC</i>	92235-4M400	9.80	X	
30 RR PANEL-END LOWER <i>BA ✓</i>	79120-5TT0A	215.00	/	
31 LH REAR WHEELHOUSE FINISHER <i>? CA ✓</i>	84953-5TT7A	638.00	/	
32 GARNISH END PANEL <i>CA ✓</i>	84990-5TA0B	52.30	/	
33 BOX-LUGGAGE S/TYRE HOUSING <i>? X SU</i>	84975-5TA0A	279.60		
34 BOARD ASSY S/TYRE HOUSING <i>de ✓</i>	84906-5TA0A	528.00	/	
35 GARNISH ASSY LH REAR (TOP) WHEELHOUSE <i>? X SU</i>	76912-5TA0A	144.20		
36 FACE-RR BUMPER <i>de ✓</i>	85022-5TT6H	1414.00	/	
37 BRACKET-BUMPER LH REAR <i>? X SU</i>	85271-5TA0A	32.50	X	
38 BRACKET-BUMPER RH REAR <i>? X SU</i>	85270-5TA0A	32.50	X	
39 REAR BUMPER LH SIDE BRACKET <i>? X SVC</i>	85221-5TA0A	32.50	X	
40 REAR BUMPER LH SIDE BRACKET <i>? X SVC</i>	85221-5TT5A	26.00	X	
41 REAR BUMPER RH SIDE BRACKET <i>? X SVC</i>	85220-5TA0A	32.50	X	
42 REAR BUMPER RH SIDE BRACKET <i>? X SVC</i>	85220-5TT5A	26.00	X	
43 GROMET BUMPER \$1.60 EA X 05 <i>re ✓</i>	85099-1MA0A	8.00	/	
44 CLIP BUMPER/FINISHER \$1.30 EA X 27 <i>m ✓</i>	01553-05933	35.10	/	
45 GROMMET BUMPER \$2.70 EA X 12 <i>m ✓</i>	63846-5V000	32.40	/	
46 SHIELD ASSY LH REAR SIDE <i>repair</i>	85231-5TT0C	384.90	X R	
47 SHIELD ASSY REAR SIDE RH <i>repair</i>	85230-5TT0C	384.90	X R	
48 MOUL-RR BUMPER LH (BLACK) <i>? X SU</i>	85075-5TT0A	359.70	X	
49 MOUL-RR BUMPER RH (BLACK) <i>? X SU</i>	85074-5TT0A	359.70	X	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
50 DOOR BACK (TOP) <i>bu</i> ✓	9001A-5TK2C	4015.00	✓	
51 A FIN BACK DOOR CENTER <i>de</i> ✓	90810-5TA0A	797.20	✓	
52 DOOR BACK <i>de</i> ✓	K010M-5TAAA	1742.00	✓	
53 W/STRIP-BK DOOR (TOP) <i>ne</i> ✓	90831-5TA0A	141.80	✓	
54 WEATHER STRIP BODY <i>ne</i> ✓	90830-5TA0A	106.40	✓	
55 HINGE ASSY-BACK RH ? <i>fsu</i>	90400-5TA0B	73.20	X	
56 HINGE ASSY-BACK LH ? <i>fsu</i>	90401-5TA0B	73.20	X	
57 A FIN BACK DOOR (SERENA) <i>ca</i> ✓	90810-5TD5C	797.20	✓	
58 A LOCK LIFT LOWER <i>bt</i> ✓	90502-5TA0C	199.80	✓	
59 STRIKER-TAIL GATE (TOP) <i>bt</i> ✓	90570-5TA0A	34.80	✓	
60 A LOCK LIFT (TOP) ? <i>fsu</i>	90502-5TA1B	199.80	X	
61 BRACKET, LOCK (TOP) TAILGATE ? <i>fsu</i>	905C0-5TA0A	39.00	X	
62 GARNISH ASSY, RR TOP WIPER <i>ca</i> ✓	90904-5TA2A	192.90	✓	
63 FINISHER TAILGATE REAR TRIMBOARD <i>ca</i> ✓	90901-5TA0A	297.90	✓	
64 FIN-TAIL GATE (LOWER) CENTER ? <i>ca</i> ✓	90900-5TA0A	187.50	✓	
65 AIR SPOILR-RR, LH REAR ? <i>fsu</i>	96033-5TH0A	189.20	X	
66 BRKT RR SPOILER LH ? <i>fsu</i>	96043-5TH0A	103.00	X	
67 AIR SPOILR-RR, RH ? <i>fsu</i>	96032-5TH0A	189.20	X	
68 BRKT RH REAR SPOILER ? <i>fsu</i>	96042-5TH0A	103.00	X	
69 EMBLEM REAR <i>ne</i> ✓	90886-5TA0B	79.90	✓	
70 EMBLEM-REAR <i>ne</i> ✓	90897-5TA0A	50.90	✓	
71 SUNDRIES <i>ne</i> ✓	NPN			to 200.00
72 EMBLEM-REAR <i>ne</i> ✓	90892-5TL0A	94.40	✓	
73 S/TYRE HOUSING ? <i>repair</i>	G4514-5TAMA	492.10	XR	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		17934.30	0.00	3423.80
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		3586.86	0.00	0.00
GRAND TOTAL		14347.44	0.00	3423.80
OVERALL TOTAL		17771.24		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SHQ6601H

TOTAL LABOUR CHARGES	11535.00	
TOTAL SPARE PARTS CHARGES	17771.24	
GRAND TOTAL	29306.24 *	31,570.64

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Rasul - Hp 90110078
9 days + 2 = 11 days + 2 days (sunday) = 13 days
28/01/2021 @ 1450
Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: