

12/02/2020

REF: CS/EQI21001331/R1vd3

Special Instruction:

ASS. REC. BY:

SURVEYOR: RASUL

ASSIGNMENT (Office)

From (Person): JAIME TAY

of EQI

Date/Time: 28/01/2021@10.43AM

Estimated Cost:

Bill to:

OD  TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMQ 6601H

Insured: GBD 4600Y

at Workshop m/s TAN CHONG MOTOR

Tel: 6703 8914

of 913 BUKIT TIMAH ROAD

Policy No:

Claim No: DM21HO00155/JT

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 25/01/2021

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 11.16AM@28/01/21

Person Contacted: LAWRENCE

Vehicle  IN  OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SMQ 6601H-X
	GBD 4600Y-X
29/1/21	Email preli revised to Jaime
25/2/21	Final fig \$19,786.26 confirmed by email (Red 11,784.38.37%)