

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0029/2021
DATE : 27-JAN-2021

6/02/2021

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

D/S

OWNER'S NAME : MR FUM YONG YUEN
ADDRESS : BLK 792 WOODLANDS AVENUE 6
#13-691
S(730792)
TELEPHONE NO : 85009239

RASUL

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBD4600Y
VEHICLE NO : SMQ6601H
MODEL CODE : EDWARW9C27HWA-----
MODEL/YEAR : NISSAN SERENA E-POWER 1.2 HIGHWAY STAR MY2019
ENGINE NO : HR12116390K LB10
CHASSIS NO : JN1EBAC27Z0000261
MILEAGE : 30588 KM
DATE IN : 27/01/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 25/01/2021

804. 13 days.

2 \$1040/-

11 + 2 Sunday = 13 DAY

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CRP	CONDUCT CONSULT, RESET & PROGRAMMING	240.00	240.00
2	PDVR	SUPPLY & INSTALL PAPAGO GS360DVR	357.00	357.00
3	PSC	PULL/STRAIGHTEN CHASSIS	350.00	.00
4	RIBH	REMOVE/INSTALL BLOWER & HEATER UNIT TO FACILITATES REPAIRS	240.00	240.00
5	RIEMA	REMOVE/INSTALL EXHAUST MUFFLER ASSY	240.00	.00
6	RISCC	REMOVE/INSTALL SEAT & CUSHION CARPET	240.00	240.00
7	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	120.00
8	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 05	600.00	120.00
9	RRWIRE	REMOVE/REPAIR WIRE HARDNESS (REVERSE SENSOR)	240.00	.00
10	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	110.00
11	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 05	500.00	100.00
12	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	150.00
13	UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	240.00
14	ZZ/001	REPAIR LH/RH REAR FENDER AND RENEAR TAILGATE(TOP/BOTTOM), END PANEL, S/TYRE HOUSING, REAR BUMPER	3900.00	2340.00
15	ZZ/002	S/PAINT REAR PORTION, CHASIS FRAME, S/TYRE HOUSING AND LH/RH REAR PILLAR	3000.00	1750.00
16	ZZ/003	R/I REAR WHEELHOUSE FINISHER, PILLAR FINISHER TO ASSIST REPAIR	240.00	240.00
17	ZZ/004	DISCONNECT/CONNET POWER SUPPLY	240.00	240.00
18	ZZ/005	SUPPLY AND RENEW REAR NO PLATE (SMART PLATE WITH CASING) LONG		
19	ZZ/006	CHECK LIGHTING	48.00	48.00
20	ZZ/007	VACUMM LOOSE GLASS (REAR WINDSCREEN)	240.00	240.00
21	ZZ/008	(REPAIR LH/RH REAR PILLAR)		

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
22	ZZ/009	TRANSFER REAR TAIL MECHNICAL PARTS OR RENEW (TOP/BOTTOM)	240.00	240.00
23	ZZ/10	CHARGE AND DISCHARE A/CON GAS - SUPPLEMENTARY	120.00	120.00
TOTAL LABOUR CHARGES			11655.00	7135.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 COVER HIGH MTG 3RD BRAKE LIGHT GARNISH - SUPPLEMEN	26598-5TA5A	61.20			OK <i>me</i>
2 SHIELD ASSY LH REAR SIDE	85231-5TT0C	384.90			X
3 FINISHER RH REAR WHEELHOUSE - SUPPLEMENTARY	84952-5TN0A	638.00			OK <i>ph</i>
4 COOLING UNIT LH REAR - SUPPLEMENTARY	27400-5TA0B			900.00	OK <i>ph</i>
5 CARPET FLOOR - SUPPLEMENTARY	74906-5TL1A	545.20			OK <i>ph</i>
6 HANDLE-PULL TAILGATE	90940-4N000	19.60			OK
7 LICENSE PLATE LAMP \$80.20 EA X 02	26510-8990E	160.40			X
8 MUFFLER ASSY	20350-5TLOB			828.00	X
9 GASKET-EXHAUST	20691-19B0A			4.40	X
10 MOUNTING EXHAUST	20651-CY00B			21.80	X
11 MOUNTING EXHAUST	20651-4N000			11.20	X
12 HARNESS-CORNER SENSOR REVERSE	24093-5TTOB	194.40			X
13 SENSOR ASSY REAR BUMPER (OUTER) \$232.00 EA X 02	28438-5TT1C			464.00	X
14 COVER REAR BUMPER SENSOR (OUTER) \$96.30 EA X 02	28533-5TT1D			192.60	X
15 SENSOR BUMPER CENTER \$232.00 EA X 02	28438-5TT1B			464.00	OK
16 COVER REAR BUMPER CENTER SENSOR \$72.50 EA X 02	28533-5ZA0A			145.00	OK
17 LAMP COMB RR,LH	26555-5TT0A	560.30			X
18 LAMP COMB RR,RH	26550-5TT0A	560.30			OK
19 GROMET TAILGATE \$4.90 EA X 02	26557-2U001	9.80			OK
20 GROMET TAILGATE \$4.90 EA X 02	26557-2U000	9.80			OK
21 LAMP ASSY-STOP 3RD	26590-5TA0A			237.50	X
22 CAMERA ASSY ALL VIEW (REAR)	28442-5TA3A	750.00			X
23 ARM ASSY-RR WIPER	28780-5AL0A			59.40	X
24 REFILL-RR WIPER	28795-5AA0A			12.50	X
25 COVER-ARM,BACK WIPER	28782-5AA0A			11.20	X

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
26 MOTOR-WIPER	28710-5TA0B			479.70	X
27 END PANEL TOP	75610-5TA0A			242.50	OK
28 PROTECTOR-RH FENER REAR	76748-5TF0A	117.70			X
29 CLIP FENDER \$1.30 EA X 06	01553-05131	7.80			OK
30 DRAFTER-AIR LH REAR	76804-5TA1A	67.40			X
31 VALVE LH REAR FENDER \$4.90 EA X 02	92235-4M400	9.80			X
32 RR PANEL-END LOWER	79120-5TT0A	215.00			OK
33 LH REAR WHEELHOUSE FINISHER	84953-5TT7A	638.00			OK <i>photo</i>
34 GARNISH END PANEL	84990-5TA0B	52.30			OK
35 BOX-LUGGAGE S/TYRE HOUSING	84975-5TA0A	279.60			X
36 BOARD ASSY S/TYRE HOUSING	84906-5TA0A	528.00			OK <i>photo</i>
37 GARNISH ASSY LH REAR (TOP) WHEELHOUSE	76912-5TA0A	144.20			X
38 FACE-RR BUMPER	85022-5TT6H	1414.00			OK
39 BRACKET-BUMPER LH REAR	85271-5TA0A	32.50			X
40 BRACKET-BUMPER RH REAR	85270-5TA0A	32.50			X
41 REAR BUMPER LH SIDE BRACKET	85221-5TA0A	32.50			X
42 REAR BUMPER LH SIDE BRACKET	85221-5TT5A	26.00			X
43 REAR BUMPER RH SIDE BRACKET	85220-5TA0A	32.50			X
44 REAR BUMPER RH SIDE BRACKET	85220-5TT5A	26.00			X
45 GROMET BUMPER \$1.60 EA X 05	85099-1MA0A	8.00			OK
46 CLIP BUMPER/FINISHER \$1.30 EA X 27	01553-05933	35.10			OK
47 GROMMET BUMPER \$2.70 EA X 12	63846-5V000	32.40			OK
48 SHIELD ASSY REAR SIDE RH	85230-5TT0C	384.90			X
49 MOUL-RR BUMPER LH (BLACK)	85075-5TT0A	359.70			X

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
50	DOOR BACK (TOP)	9001A-5TK2C	4015.00			OK
51	A FIN BACK DOOR CENTER	90810-5TA0A	797.20			OK
52	DOOR BACK	K010M-5TAAA	1742.00			OK
53	W/STRIP-BK DOOR (TOP)	90831-5TA0A	141.80			OK
54	WEATHER STRIP BODY	90830-5TA0A	106.40			OK
55	HINGE ASSY-BACK RH	90400-5TA0B	73.20			X
56	HINGE ASSY-BACK LH	90401-5TA0B	73.20			X
57	A FIN BACK DOOR (SERENA)	90810-5TD5C	797.20			OK
58	A LOCK LIFT LOWER	90502-5TA0C	199.80			OK
59	STRIKER-TAIL GATE (TOP)	90570-5TA0A	34.80			OK
60	A LOCK LIFT (TOP)	90502-5TA1B	199.80			X
61	BRACKET, LOCK (TOP) TAILGATE	905C0-5TA0A	39.00			X
62	GARNISH ASSY, RR TOP WIPER	90904-5TA2A	192.90			OK
63	FIN-TAIL GATE (LOWER) CENTER	90900-5TA0A	187.50			OK
64	AIR SPOILR-RR,LH REAR	96033-5TH0A	189.20			X
65	BRKT RR SPOILER LH	96043-5TH0A	103.00			X
66	AIR SPOILR-RR,RH	96032-5TH0A	189.20			X
67	BRKT RH REAR SPOILER	96042-5TH0A	103.00			X
68	EMBLEM REAR	90886-5TA0B	79.90			OK
69	EMBLEM-REAR	90897-5TA0A	50.90			OK
70	SUNDRIES	NPN			40.00	OK
71	EMBLEM-REAR	90892-5TL0A	94.40			OK
72	REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG	RLP			50.00	OK
73	INSULATOR HEAT S/TYRE HOUSING	G5930-89904	132.10			X
74	PROTECTOR-LH REAR FENDER	76749-5TF0A	117.70			X

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
75 MOUL-RR BUMPER RH (BLACK)	85074-5TT0A	359.70			X
76 FINISHER TAILGATE REAR TRIMBOARD	90901-5TA0A	297.90			OK
77 S/TYRE HOUSING	G4514-5TAMA	492.10			X
SUB TOTAL		13512.20	0.00	1841.50	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		2702.44	0.00	0.00	
GRAND TOTAL		10809.76	0.00	1841.50	
OVERALL TOTAL		12651.26			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SMQ6601H

NETT ITEM	13512.20
LESS 20.00%)	-2702.44
NETT AMOUNT	10809.76
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	1841.50
LESS .00%)	0.00
SPECIAL NETT AMOUNT	1841.50
TOTAL LABOUR CHARGES	7135.00
TOTAL SPARE PARTS CHARGES	12651.26
TOTAL CHARGES	19786.26
ADD 7 % GST	1385.04
GRAND TOTAL	21171.30

5-Feb-2021

INS/IC/LAW/0029/2021

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
Singapore 069110

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SMQ6601H
POLCY NO. : -

Further to our claim we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

<u>Replacement of Damaged Items</u>		
1	CHARGE AND DISCHARE A/CON GAS	\$120.00
2	FINISHER RH REAR WHEELHOUSE	\$638.00 NETT
3	CARPET FLOOR	\$545.20 NETT
4	COOLING UNIT LH REAR	\$900.00 S/NETT
5	COVER HIGH MTG 3RD BRAKE LIGHT GARNISH	\$61.20 NETT

TOTAL \$ 2,264.40

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully

TAN CHONG MOTOR SALES PTE LTD

Lawrence Teo
Insurance Claim Dept

Cc: Surveryor