

ASS. REC. BY: Rome


REF: CS/EQ1 21001331/R1vd3

478

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMA 6601H
 at Workshop m/s TAN CHONG MOTOR
 of 913, BUKIT TIMAH RD
 Insured: EQ
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 111K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMA 6601H Yr Regn: 2019 / NOV
 Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: NISSAN SERENA 1.2 HW SMC c.c. 1198
 Colour: GOLD A/C: Insured / Std / NI / NA
 Sp. Reading: 30589 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN1EBA C272000V261
 Gen. Cond: Good / (Fair) / Poor / Burnt
 Steering: In order / Jaimmed / Leaked / Burnt or _____
 Brake: In order / Jaimmed / Leaked / Burnt or _____
 Modi: Nil / (Rim) / STD A/Rim or _____
 Tyre Size: F: 195/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 25/01/2021 D.O.I. 28/01/2021
 Survey held at TAN CHONG
 Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit = 57K</u>

Date/Time, File Pass to? : Prell. Report
 : Final Report
 Date/Time, File Return to?
 2) _____
 Rep. Format: _____
 Lump Sum / L.S. (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee:	
Transportation:	
\$ + RS. SI	
Photos	
Others	
TOTAL	

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0029/2021
DATE : 27-JAN-2021

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MR FUM YONG YUEN
ADDRESS : BLK 792 WOODLANDS AVENUE 6
#13-691
S(730792)
TELEPHONE NO : 85009239

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBD4600Y
VEHICLE NO : SMQ6601H
MODEL CODE : EDWARW9C27HWA-----
MODEL/YEAR : NISSAN SERENA E-POWER 1.2 HIGHWAY STAR MY2019
ENGINE NO : HR12116390K LB10
CHASSIS NO : JN1EBAC27Z0000261
MILEAGE : 30588 KM
DATE IN : 27/01/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 25/01/2021

15200
27/01/2021

DIRECT SETTLEMENT
OWNER CLAIMING LOSS OF USE / RENTAL
CAR AT WORKSHOP / CAR ~~NOT~~ AT WORKSHOP
KINDLY REVERT TO ME ASAP
EMAIL : lawrenceteo@tanchong.com
H/P : 94568832 FAX : 64697472

*OWNER using
LAWYER TO
CLAIM
Body Injury
CAR Ins*

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CRP	CONDUCT CONSULT, RESET & PROGRAMMING	240.00	/
2	PDVR	SUPPLY & INSTALL PAPAGO GS360DVR <i>MB</i>	357.00	/
3	PSC	PULL/STRAIGHTEN CHASSIS	350.00	?
4	RIBH	REMOVE/INSTALL BLOWER & HEATER UNIT TO FACILITATES REPAIRS	240.00	?
5	RIEMA	REMOVE/INSTALL EXHAUST MUFFLER ASSY	240.00	?
6	RISCC	REMOVE/INSTALL SEAT & CUSHION CARPET	240.00	?
7	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	/
8	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 05	600.00	120
9	RRWIRE	REMOVE/REPAIR WIRE HARDNESS (REVERSE SENSOR)	240.00	?
10	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	/
11	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 05	500.00	100
12	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	/
13	UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	/
14	ZZ/001	REPAIR LH/RH REAR FENDER AND RENEAR TAILGATE (TOP/BOTTOM), END PANEL, S/TYRE HOUSING, REAR BUMPER @290	3900.00	1950
15	ZZ/002	S/PAINT REAR PORTION, CHASIS FRAME, S/TYRE HOUSING AND LH/RH REAR PILLAR @250	3000.00	1500
16	ZZ/003	R/I REAR WHEELHOUSE FINISHER, PILLAR FINISHER TO ASSIST REPAIR	240.00	?
17	ZZ/004	DISCONNECT/CONNECT POWER SUPPLY	240.00	/
18	ZZ/005	SUPPLY AND RENEW REAR NO PLATE (SMART PLATE WITH CASING) LONG		
19	ZZ/006	CHECK LIGHTING	48.00	/
20	ZZ/007	VACUUM LOOSE GLASS (REAR WINDSCREEN)	240.00	/
21	ZZ/008	(REPAIR LH/RH REAR PILLAR)		

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
22	ZZ/009	TRANSFER REAR TAIL MECHANICAL PARTS OR RENEW (TOP/BOTTOM)	240.00	/
TOTAL LABOUR CHARGES			11535.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 HANDLE-PULL TAILGATE <i>de ✓</i>	90940-4N000	19.60		
2 LICENSE PLATE LAMP \$80.20 EA X 02 <i>?</i>	26510-8990E	160.40		
3 REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG RLP <i>LA ✓</i>				50.00
4 MUFFLER ASSY <i>?</i>	20350-5TLOB			828.00
5 GASKET-EXHAUST <i>?</i>	20691-19B0A			4.40
6 MOUNTING EXHAUST <i>?</i>	20651-CY00B			21.80
7 MOUNTING EXHAUST <i>?</i>	20651-4N000			11.20
8 HARNESS-CORNER SENSOR REVERSE <i>?</i>	24093-5TTOB	194.40		
9 SENSOR ASSY REAR BUMPER (OUTER) \$232.00 EA X 02 <i>?</i>	28438-5TT1C			464.00
10 COVER REAR BUMPER SENSOR (OUTER) \$96.30 EA X 02 <i>?</i>	28533-5TT1D			192.60
11 SENSOR BUMPER CENTER \$232.00 EA X 02 <i>new ✓</i>	28438-5TT1B			464.00
12 COVER REAR BUMPER CENTER SENSOR \$72.50 EA X 02 <i>new ✓</i>	28533-5ZA0A			145.00
13 LAMP COMB RR, LH <i>?</i>	26555-5TTOA	560.30		
14 LAMP COMB RR, RH <i>CR ✓</i>	26550-5TTOA	560.30		
15 GROMET TAILGATE \$4.90 EA X 02 <i>new ✓</i>	26557-2U001	9.80		
16 GROMET TAILGATE \$4.90 EA X 02 <i>new ✓</i>	26557-2U000	9.80		
17 LAMP ASSY-STOP 3RD <i>X</i>	26590-5TA0A			237.50
18 CAMERA ASSY ALL VIEW (REAR) <i>?</i>	28442-5TA3A	750.00		
19 ARM ASSY-RR WIPER <i>?</i>	28780-5AL0A			59.40
20 REFILL-RR WIPER <i>?</i>	28795-5AA0A			12.50
21 COVER-ARM, BACK WIPER <i>?</i>	28782-5AA0A			11.20
22 MOTOR-WIPER <i>?</i>	28710-5TA0B			479.70
23 END PANEL TOP <i>BT ✓</i>	75610-5TA0A			242.50
24 INSULATOR HEAT S/TYRE HOUSING <i>? repair</i>	G5930-89904	132.10		
25 PROTECTOR-LH REAR FENDER <i>X</i>	76749-5TF0A	117.70		

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 PROTECTOR-RH FENER REAR X	76748-5TF0A	117.70		
27 CLIP FENDER \$1.30 EA X 06 <i>re ✓</i>	01553-05131	7.80		
28 DRAFTER-AIR LH REAR <i>re X</i>	76804-5TA1A	67.40		
29 VALVE LH REAR FENDER \$4.90 EA X 02 X	92235-4M400	9.80		
30 RR PANEL-END LOWER <i>BT ✓</i>	79120-5TT0A	215.00		
31 LH REAR WHEELHOUSE FINISHER ?	84953-5TT7A	638.00		
32 GARNISH END PANEL <i>ca ✓</i>	84990-5TA0B	52.30		
33 BOX-LUGGAGE S/TYRE HOUSING ?	84975-5TA0A	279.60		
34 BOARD ASSY S/TYRE HOUSING <i>de ✓</i>	84906-5TA0A	528.00		
35 GARNISH ASSY LH REAR (TOP) WHEELHOUSE ?	76912-5TA0A	144.20		
36 FACE-RR BUMPER <i>de ✓</i>	85022-5TT6H	1414.00		
37 BRACKET-BUMPER LH REAR ?	85271-5TA0A	32.50		
38 BRACKET-BUMPER RH REAR ?	85270-5TA0A	32.50		
39 REAR BUMPER LH SIDE BRACKET ?	85221-5TA0A	32.50		
40 REAR BUMPER LH SIDE BRACKET ?	85221-5TT5A	26.00		
41 REAR BUMPER RH SIDE BRACKET ?	85220-5TA0A	32.50		
42 REAR BUMPER RH SIDE BRACKET ?	85220-5TT5A	26.00		
43 GROMET BUMPER \$1.60 EA X 05 <i>re ✓</i>	85099-1MA0A	8.00		
44 CLIP BUMPER/FINISHER \$1.30 EA X 27 <i>m ✓</i>	01553-05933	35.10		
45 GROMMET BUMPER \$2.70 EA X 12 <i>m ✓</i>	63846-5V000	32.40		
46 SHIELD ASSY LH REAR SIDE <i>repair</i>	85231-5TT0C	384.90		
47 SHIELD ASSY REAR SIDE RH <i>repair</i>	85230-5TT0C	384.90		
48 MOUL-RR BUMPER LH (BLACK) ?	85075-5TT0A	359.70		
49 MOUL-RR BUMPER RH (BLACK) ?	85074-5TT0A	359.70		

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
50 DOOR BACK (TOP) <i>bu</i>	9001A-5TK2C	4015.00		
51 A FIN BACK DOOR CENTER <i>de</i>	90810-5TA0A	797.20		
52 DOOR BACK <i>de</i>	K010M-5TAAA	1742.00		
53 W/STRIP-BK DOOR (TOP) <i>re</i>	90831-5TA0A	141.80		
54 WEATHER STRIP BODY <i>re</i>	90830-5TA0A	106.40		
55 HINGE ASSY-BACK RH ?	90400-5TA0B	73.20		
56 HINGE ASSY-BACK LH ?	90401-5TA0B	73.20		
57 A FIN BACK DOOR (SERENA) <i>ca</i>	90810-5TD5C	797.20		
58 A LOCK LIFT LOWER <i>bt</i>	90502-5TA0C	199.80		
59 STRIKER-TAIL GATE (TOP) <i>bt</i>	90570-5TA0A	34.80		
60 A LOCK LIFT (TOP) ?	90502-5TA1B	199.80		
61 BRACKET, LOCK (TOP) TAILGATE ?	905C0-5TA0A	39.00		
62 GARNISH ASSY, RR TOP WIPER <i>ca</i>	90904-5TA2A	192.90		
63 FINISHER TAILGATE REAR TRIMBOARD <i>ca</i>	90901-5TA0A	297.90		
64 FIN-TAIL GATE (LOWER) CENTER ?	90900-5TA0A	187.50		
65 AIR SPOILR-RR,LH REAR ?	96033-5TH0A	189.20		
66 BRKT RR SPOILER LH ?	96043-5TH0A	103.00		
67 AIR SPOILR-RR,RH ?	96032-5TH0A	189.20		
68 BRKT RH REAR SPOILER ?	96042-5TH0A	103.00		
69 EMBLEM REAR <i>re</i>	90886-5TA0B	79.90		
70 EMBLEM-REAR <i>re</i>	90897-5TA0A	50.90		
71 SUNDRIES <i>re</i>	NPN			<i>to 200.00</i>
72 EMBLEM-REAR <i>re</i>	90892-5TL0A	94.40		
73 S/TYRE HOUSING ? <i>re</i>	G4514-5TAMA	492.10		

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ6601H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		17934.30	0.00	3423.80
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		3586.86	0.00	0.00
GRAND TOTAL		14347.44	0.00	3423.80
OVERALL TOTAL		17771.24		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMQ6601H

TOTAL LABOUR CHARGES	11535.00
TOTAL SPARE PARTS CHARGES	17771.24
GRAND TOTAL	29306.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Resul - Hp 90010078
9 days
28/01/2021 @ 1450
Resury before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

slc



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	26/01/2021 15:40 (SGT)
Date of Accident	25/01/2021 16:40 (SGT)
Exact Location of Accident	Serangoon Rd, Singapore
Additional Location Information	ENTRANCE TO KWONG WAI SHIU HOSPITAL
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMQ6601H

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	FUM YONG YUEN
NRIC No	SXXXX417F
Email Address	FUMFRANCIS@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-90283096
Alternative Phone No	+65-90283096

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Serena
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire

INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5114191280-01
Cover Note Number	-

DRIVER

Name of Driver	FUM YONG YUEN
NRIC No	SXXXX417F
Date Of Birth	27/11/1969
Occupation	Outdoor

Driving Pass
experience
er
ite Number
it. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

26/02/1993
27 YEARS AND 11 MONTHS
Male
(Phone) +65-90283096
+65-90283096
FUMFRANCIS@YAHOO.COM.SG
BLK 792 WOODLANDS AVE 6 #13-691
-
730792
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? Yes
Was any injured conveyed to hospital by ambulance? No
Was any other material or property damaged? Yes
Number of Passengers (Including Driver) 2
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance? No

PASSENGER 1

Name MISS LOW
Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
Police Station Name Traffic Police
Police Station Phone No (Phone) +65-65470000
Alt. Police Station Phone No (Fax) +65-65474900
Police Station Address 10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE ATTACHED POLICE REPORT.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number GBD4600Y
Vehicle Manufacturer Nissan
Vehicle Model Nv350
Vehicle Variant -

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	417F
Vehicle No.:	SMQ6601H
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jan 2021
Vehicle Make:	NISSAN
Vehicle Model:	SERENA 1.2L HIGHWAY STAR PREMIUM E-POWER
Primary Colour:	Gold
Manufacturing Year:	2019
Engine No.:	HR12116390K
Chassis No.:	JN1EBAC27Z0000261
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$30,076.00
Original Registration Date:	28 Nov 2019
First Registration Date:	28 Nov 2019
Transfer Count:	0
Actual ARF Paid:	\$24,107.00
PARF ELIGIBILITY	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2029
PARF Rebate Amount:	\$18,080.00
COE ELIGIBILITY	
COE Expiry Date:	27 Nov 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,009.00
COE Rebate Amount:	\$35,340.00
Total Rebate Amount:	\$53,420.00

The information contained herein is correct as at 28 Jan 2021

OK



Merimen e-Claims



Used 2020 Nissan Serena e-POW



PARF/COE

art.com/used_cars/info.php?ID=920016&DL=2202

► Nissan Serena e-POWER Hybrid 1.2A Highway Star Premium

Overview

Financial

Accessories

Similar

Research

Photos

Map



HUA YANG CREDIT PTE LTD



Price	\$114,800	Fuel Type	Petrol-Electric
Depreciation [?]	\$11,300 /yr View models with similar depre	Reg Date	29-Feb-2020 (9yrs 1mth COE left)
Mileage	13,000 km	Manufactured [?]	2019
Road Tax [?]	\$860 /yr	Transmission	Auto
Dereg Value [?]	\$47,978 as of today (change)	OMV [?]	\$30,076
COE [?]	\$32,889	ARF [?]	\$24,107
Engine Cap	1,198 cc	Power	100.0 kW (134 bhp)
Curb Weight [?]	1,758 kg	No. of Owners [?]	2
Type of Vehicle	MPV		

Features

Power By 1.2L 3-cylinder In-line, Petrol-Electric, DOHC ABS, Airbags, Traction Control, Keyless Entry/Start/Stop.
View specs of the Nissan Serena e-POWER Hybrid (2019)

