



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883

Company GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

M/S : AIG Asia Pacific Insurance Pte Ltd
(MOTOR CLAIM DEPARTMENT)

Email shengyang.lim@aig.com
noormarriesa.abukassim@aig.com

Xiao Tong

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SML1316R

Date: 28.01.2021

Veh. Model HYUNDAI AVANTE AD

Reg. Date 07.05.2019

Chassis No : KMHD841CMKU910812

D.O.A : 27.01.2021

1	Front Bonnet <i>new Rep</i>	1		+ 1,971.20
2	Front Bonnet Hinges	2	145.60	+ 291.20
3	Front Bonnet Insulator	1		+ 385.90
4	Front Bonnet Lock	1		+ 235.90
5	Front Bonnet Stopper	4	8.60	+ 34.40
6	Front Bonnet Labelled	2	28.00	+ 56.00
7	Headlamp RH <i>cut 1198.80</i>	1	<i>1198.80</i>	<i>3,035.20</i>
8	Headlamp Bracket RH <i>cut</i>	1		✓ 98.60
9	Front Bumper <i>disbld</i>	1	<i>474</i>	✓ 658.20
10	Front Bumper Side Retainer <i>new RH</i>	2	86.90	<i>86.90</i> 173.80
11	Front Bumper Top Bracket RH <i>cut</i>	1		✓ 98.60
12	Front Bumper Number Plate Garnish <i>new</i>	1		+ 65.30
13	Front Bumper Radiator Grille <i>cut</i>	1	<i>628.60</i>	✓ 1,218.60
14	Front Bumper Front Bumper Signal Lamp <i>cut RH</i>	2	185.80	<i>185.80</i> 371.60
15	Front Bumper Side Strip <i>RH disbld</i>	2	92.60	<i>92.60</i> 185.20
16	Front Bumper Side Cover <i>cut RH</i>	2	98.60	<i>98.60</i> 197.20
17	Front Bumper Lower Lip <i>disbld</i>	1		✓ 295.60
18	Front Bumper Top Garnish Rubber Seal <i>new</i>	1		+ 85.20
19	Front Bumper Top Garnish <i>cut</i>	1		✓ 202.50

9,660.20

CF 9,660.20



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F

9,660.20

20	Front Bumper Air Guide <i>could</i>	1		✓ 125.80
21	Front Engine Under Cover <i>could</i>	1		✓ 356.80
22	Front Bumper Reinforcement <i>Best</i>	1		✓ 589.50
23	Front Bumper Reinforcement Striffener <i>could</i>	1		✓ 175.20
24	Front Bumper Reinforcement Sponge <i>could</i>	1		✓ 225.60
25	Front Support Panel <i>could</i>	1		✓ 987.50
26	Front Fender RH <i>Ry</i>	1		+ 1,227.70
27	Front Fender Inner Cowling RH <i>torn</i>	1		✓ 189.30
28	Front Resonator Box <i>new</i>	1		+ 158.30
29	Wiper Washer Tank <i>Del</i>	1		✓ 125.80
30	Wiper Washer Tank Motor <i>new</i>	1		+ 89.50
31	Horn <i>new</i>	1		+ 80.30
32	Radiator Assy <i>new</i>	1		+ 526.80
33	Radiator Fan Motor W Spare Tank <i>new</i>	1		+ 652.60
34	AC Condenser <i>new</i>	1		+ 746.50

6236.1
4988.88

15,917.40
less 20% 3,183.48
12,733.92

Special nett item

1	Front Number Plate With Casing <i>new Del</i>	1set		✓ 50.00
2	Front Bonnet Insulator Clips <i>new</i>	1set		+ 30.00
3	Front Bumper Clips <i>new</i>	1set		✓ 30.00
1	Front Bumper Top Garish Clips <i>new</i>	1set		20 30.00
2	Front Engine Under Cover Clips <i>new</i>	1set		✓ 30.00
3	Front Fender Cowling Clips <i>new</i>	1set		+ 30.00

\$ 12,933.92

130

C/F

\$ 12,933.92



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F \$ 12,933.92

To panel beat/straighten/realign accident affected portion.	6w	1,500.00
To respray accident affected portion.	6w	1,500.00
To conduct wiring check and repair	30	100.00
To remove/refit mechanical parts to assist repair and top up ac gas	120	150.00
To conduct headlamp alignment	30	100.00
		16,283.92

1380

Admin Lj
P/P 29/01/21
06 Eys

Supplementary: 69.44

total: 6568.32
(P/P)



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company GST Registration No : 201828067M

VEHICLE SUPPLEMENTRY

M/S : AIG Asia Pacific Insurance Pte Ltd
(MOTOR CLAIM DEPARTMENT)

Email shengyang.lim@aig.com
noormarriesa.abukassim@aig.com

Parts - (%)

SN

Labour

Lump sum

ERV

Vehicle No: SML1316R

Date: 29.01.2021

Veh. Model HYUNDAI AVANTE AD

Reg. Date 07.05.2019

Chassis No : KMHD841CMKU910812

D.O.A : 27.01.2021

1	Front Bumper Tow Cover <i>Miss</i>	1		✓ 32.60
2	Front Support Panel Air Guide RH <i>2hd</i>	1		✓ 54.20
				86.80
				Less 20%
				<u>17.36</u>
				69.44

Adrian L
01/02/21
[Signature]

Supplementary: 69.44