



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /LEOW KOK CHIEN (LIAO GUOQUAN) Reg No/Reg Date SLF3854J / 25/08/201 Date In/Mileage / 0 Chassis No KNAFZ411MH5638347 Engine No G4FGGH623508 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim D7U PLANET BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	28/01/2021/ 12:20	QUD	247 / DonBong	28203			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID, REAR BUMPER, CUT/WELD REAR END PANEL, REPAIR REAR FLOOR PANEL					499 X 1			800 2000.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST								60.00
E PNT88000 REMOVE AND INSTALL REAR SPOILER								80.00
E PNT88000 REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK								(plm) 120.00
E PNT98000 PAINT WORK SPRAY REAR FLOOR PANEL, REAR END PANEL, REAR BOOT LID, REAR SPOILER, REAR BUMPER FACE AND AFFECTED PORTION					350 X 1			790 2100.00
M SUNDRY APPLY BODY SEALANT								40 120.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
M SUNDRY PERFORM RUST PREVENTION								40 120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY SUPPLY C&C LOGO								40.00
M SUNDRY SUPPLY REAR NUMBER PLATE WITH FRAME								50.00
M SUNDRY SUNDRIES								20 50.00
M PANEL ASSY-BACK					1.00	324.00	20.00	259.20
M TRIM-TRANSVERSE RR					1.00	58.00	20.00	46.40
M PANEL ASSY-TRUNK LID					1.00	1365.00	20.00	1092.00
M LOGO ASSY-KIA SUB					1.00	37.00	20.00	29.60
M EMBLEM-CERATO					1.00	35.00	20.00	28.00
M FORTE EMBLEM					1.00	40.00	20.00	32.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /LEOW KOK CHIEN (LIAO GUOQUAN) Reg No/Reg Date SLF3854J / 25/08/201 Date In/Mileage / 0 Chassis No KNAFZ411MH5638347 Engine No G4FGGH623508 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim D7U PLANET BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	28/01/2021/ 12:20	QUD	247 / DonBong	28203			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
M	EMBLEM K3	RC			1.00	15.00	20.00	12.00
M	LATCH ASSY-TRUNK LID	X NM			1.00	23.00	20.00	18.40
M	STRIKER ASSY-TRUNK LID	X NM			1.00	18.00	20.00	14.40
M	W/STRIP-TRUNK LID OPNG	TN			1.00	100.00	20.00	80.00
M	BRACKET-RR BUMPER SIDE MTG, LH	X NM			1.00	29.00	20.00	23.20
M	BRACKET-RR BUMPER SIDE MTG, RH	X NM			1.00	29.00	20.00	23.20
M	GUARD-BUMPER REAR, RH	X NM			1.00	17.00	20.00	13.60
M	STAY-RR BUMPER LH	BT			1.00	120.00	20.00	96.00
M	STAY-RR BUMPER RH	BT			1.00	120.00	20.00	96.00
M	BRACKET-RR BEAM UPR MTG	X NM			1.00	3.00	20.00	2.40
M	BRACKET-RR BEAM UPR MTG, RH	X NM			1.00	3.00	20.00	2.40
M	ANTENNA ASSY-SMARTKEY	X NM			1.00	69.00	20.00	55.20
M	BEAM-RR BUMPER	BR			1.00	318.00	20.00	254.40
M	BRACKET-RR BEAM LWR MTG	X NM			2.00	5.00	20.00	8.00
M	BRACKET-RR BEAM LWR, CTR	X NM			1.00	5.00	20.00	4.00
M	RETAINER	X NM			4.00	2.00	20.00	6.40
M	RETAINER-BUMPER SIDE MTG	X NM			2.00	1.00	20.00	1.60
M	CLIP	RC			10.00	2.00	20.00	16.00
M	COVER-RR BUMPER	OD			1.00	688.00	20.00	550.40
M	COVER-RR BUMPER, CTR	CUT			1.00	315.00	20.00	252.00
M	COVER-RR BPR UNDER	X NM			1.00	42.00	20.00	33.60
M	WIRING HARNESS-BWS EXT	X NM			1.00	216.00	20.00	172.80
M	ULTRASONIC SENSOR ASSY-P.A.S	X NM			1.00	177.00	20.00	141.60
M	ULTRASONIC SENSOR ASSY-P.A.S	X NM			1.00	177.00	20.00	141.60
M	ULTRASONIC SENSOR ASSY-P.A.S	X NM			1.00	177.00	20.00	141.60
M	ULTRASONIC SENSOR ASSY-P.A.S	X NM			1.00	177.00	20.00	141.60
M	SPOILER-RR	X NM			1.00	590.00	20.00	472.00

estimate

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: 28/1/21, 12:30pm

DATE: 00-NM Ant

EXCESS - 7

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: 28/1/21, 12-30pm

DATE: 00-NM Ant

REMARKS: EXCESS - ?

Confirm & accepted by the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Nett 9,151.60
7% GST on 9151.60 640.61
Total Payable 9,792.21