



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/02/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5785Z
Case Reference Number	BUS/01/21/1035
Registration Date	19/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	Norsahini Bin Nor Kholis
Type of Accident	Side Swipe
Accident Date and Time	20/1/2021 2:50 AM
Accident Reported Date and Time	19/1/2021 9:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109577
Special Instruction to ARC,if any	SG5785Z - FRONT LEFT PORTION FBQ2125Y (TP) - INSURED WITH NTUC
Prepared Date and Time	26/1/2021 3:56 PM
Chassis Number	WMAA95ZZ5G7003277
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$1,060.00
Total Spray Cost	\$786.00	\$604.00
Total Spare Part Cost	\$3,662.79	\$3,608.94
Total Other Cost	\$0.00	(\$332.80)
<b>TOTAL COST</b>	<b>\$5,773.79</b>	<b>\$4,940.14</b>
<b>Lump Sum Total</b>	<b>\$5,750.00</b>	<b>\$4,950.00</b>
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>Sun Pin (LKK)</b>
ARC / Surveyor Sign Off Date	<b>26/01/2021 4:19 PM</b>	<b>27/01/2021 2:48 PM</b>
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/02/2021

User ID : CatherineLee

### Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	\$1,060.00
<b>Total Labour</b>	<b>\$1,325.00</b>	<b>\$1,060.00</b>

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	\$604.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$786.00</b>	<b>\$604.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$332.80)
<b>Total Other Costs</b>	<b>\$0.00</b>	<b>(\$332.80)</b>

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		76100001N100	DRL 5 LIGHT. LED +MODULE	1.00	\$1,446.08	10.00	\$1,301.47	Replace	Replace
6010306			FRONT AUX HEADLAMP FLASHER LH	1.00	\$904.40	10.00	\$813.96	Replace	Replace
6010151			BUMPER FRONT	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair
6010154			FRONT FLAP	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair
6009375	VM		RETAINER:MALE & FEMALE,REAR LID,MAN BUS	1.00	\$74.80	100.00	\$0.00	Replace	Not Given
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace
6010304			FRONT HEADLAMP LH	1.00	\$1,603.60	10.00	\$1,443.24	Replace	Replace
		G20.10.05.05	FRP HEADLAMP COVER LH (NS)	1.00	\$975.00	10.00	\$877.50	Replace	Replace
<b>Total</b>					<b>\$8,816.48</b>		<b>\$4,511.17</b>		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									