



AIG - OD (REVERT)
SURVEY: 28/01/21
LKK - STEVE

VEHICLE NO : SKZ 6596 R

MODEL : KIA/FORTE K3 1.6 A SX

WIP : 27921

Material	:	\$	<u>3,331.20</u>
Labour	:	\$	<u>1,700.00</u>
Sub-Total	:	\$	<u>5,031.20</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>800.00</u>
Total	:	\$	<u>4,231.20</u>
GST 7%	:	\$	<u>296.18</u>
Grand Total	:	\$	<u>4,527.38</u>

Finalise By/Date : Wanny on 05/02/21



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (wk end)

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 29/01/2021	Cust No/Name /Seah Min Fann Reg No/Reg Date SKZ6596R / 29/01/2016 Date In/Mileage 29/01/2021/ 63287 Chassis/Package KNAFZ411MF5537893 /KC17RP Engine No G4FGFH600855 Make/Model KIA/FORTE K3 1.6 A SX ADQ Colour/Trim SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/02/2021/ 17:19	BLC	884 / Lauro Songcuan	27921

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER, FRONT FENDER LH				600.00 ✓
E PNT88000 REMOVE & INSTALL PARKING SENSOR				100.00 ✓
E PNT98000 SPRAY PAINT FOR FRONT BUMPER, FRONT FENDER LH				700.00 ✓
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00 ✓
A 90000001 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
S SPECIALISTJOB LABOUR TO TRANSFER LH FRONT SPORT RIM WITH VALVE SUPPLY				30.00 ✓
X EXC EXCESS FOR OWN DAMAGE CLAIM				-800.00
X COVER-FR BUMPER ✓	1.00	728.00	20.00	582.40 ✓
X BRACKET-FR BUMPER SIDE MTG,LH ✓	1.00	13.00	20.00	10.40 ✓
X PANEL-FENDER,LH ✓	1.00	435.00	20.00	348.00 ✓
X GUARD ASSY-FRONT WHEEL,LH ✓	1.00	109.00	20.00	87.20 ✓
X LAMP ASSY-HEAD,LH ✓	1.00	1870.00	20.00	1496.00 ✓
X WHEEL ASSY-ALUMINIUM ✓	1.00	958.00	20.00	766.40 ✓
X LOGO ASSY-KIA SUB → <i>supp.</i>	1.00	51.00	20.00	40.80 X
Z TEXT OD CLAIM AIG - TP RECOVERY FCIL DOA: 22/01/2021 SURVEY: STEVE (LKK) 28/01/2021 05 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,331.20			
Labour	1,670.00			
Standard Menu	0.00	7% GST on	4231.20	296.13
Specialist Job	30.00			
Diagnostics Job	0.00			
Sundry/Others	-800.00			
Total(w/o GST)	4,231.20		Total Payable	4,527.38

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SKZ 6596 R

<u>Material</u>		<u>Cost \$</u>
1	Logo Assy- KIA Sub	51.00 / nec
	20% Discount	10.20
		40.80
	7% GST	2.86
	Total	43.66

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SK2 6596RWIP: 27921

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Logo "KIA"	? / SUPP		✓ MC	Seen 1/2/21
2		? / SUPP			
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: K3SURVEYOR: Steve

Work Order: R001343
 License: skz 6596 r
 Technician: 810119 kfsan
 Mileage: 71014
 Date: 4.2.21 14:17

Kia : Cerato/Forte : 2013-19 (YD/YDm)

Front : Left

Actual	Before	Specified Range
-0°13'	-0°13'	-0°52' 0°08'
3°45'	3°45'	3°31' 4°31'
0°03'	0°03'	-0°03' 0°09'
13°27'	13°27'	13°06' 14°06'
13°14'	13°14'	12°14' 14°14'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°50'	-0°50'	-0°52' 0°08'
4°32'*	4°32'*	3°31' 4°31'
0°00'	0°00'	-0°03' 0°09'
13°27'	13°27'	13°06' 14°06'
12°37'	12°37'	12°14' 14°14'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°38'	0°37'	
-0°47'	-0°47'	
0°00'	0°00'	
0°03'	0°03'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°01'	-1°01'	-2°00' -1°00'
0°17'	0°17'	0°00' 0°27'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-2°05'*	-2°05'*	-2°00' -1°00'
0°13'	0°13'	0°00' 0°27'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
1°04'	1°04'	
0°30'	0°30'	0°00' 0°54'
0°02'	0°02'	

* This value is not within specification. Tire wear, handling and safety problems may result.

Work Order: R001343
 License: skz 6596 r
 Technician: 810119 kfsan
 Mileage: 71014
 Date: 4.2.21 14:17

Kia : Cerato/Forte : 2013-19 (YD/YDm)

Front : Left

Actual	Before	Specified Range
-0°13'	-0°13'	-0°52' 0°08'
3°45'	3°45'	3°31' 4°31'
0°03'	0°03'	-0°03' 0°09'
13°27'	13°27'	13°06' 14°06'
13°14'	13°14'	12°14' 14°14'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°50'	-0°50'	-0°52' 0°08'
4°32'*	4°32'*	3°31' 4°31'
0°00'	0°00'	-0°03' 0°09'
13°27'	13°27'	13°06' 14°06'
12°37'	12°37'	12°14' 14°14'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°37'	0°37'	
-0°47'	-0°47'	
0°00'	0°00'	
0°03'	0°03'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°01'	-1°01'	-2°00' -1°00'
0°17'	0°17'	0°00' 0°27'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-2°05'*	-2°05'*	-2°00' -1°00'
0°13'	0°13'	0°00' 0°27'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
1°04'	1°04'	
0°30'	0°30'	0°00' 0°54'
0°02'	0°02'	

* This value is not within specification. Tire wear, handling and safety problems may result.



HOME

Online



CERATO/FORTE../2015/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



CLU



BCM



SJB

11/11

System	Status	Result
EPS	No Current DTC	Good
SMK	No Current DTC	Good
PSM	No Current DTC	Good
SJB	No Current DTC	Good
BCM	No Current DTC	Good
CLU	No Current DTC	Good

System	DTC	Description	State
ABSESP	C1260	Steering Angle Sensor Circuit-Signal	History

S/W Ver.

M-E-K-01-00-0238

VCI Ver.

02.49

ECU Ver.

M-E-K-01-00-0179

OS Ver.

Android 10

HOME Online  CERATO/FORTE../2015/G 1.6 MPI.. VCI  


 **Fault Code Searching**

Rescan

Erase All DTC

Go to DTC

Save



9/9

System	Status	Result
AT	No Current DTC	Good
ABSESP	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good
SMK	No Current DTC	Good
BCM	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0238

VCI Ver.

02.49

ECU Ver.

M-E-K-01-00-0179

OS Ver.

Android 10

HOME
 Online

CERATO/FORTE../2015/G 1.6 MPI..

VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

SJB
 PSM
 CLU

9/9

System	Status	Result
AT	No Current DTC	Good
ABSESP	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good
SMK	No Current DTC	Good
BCM	No Current DTC	Good

System	DTC	Description	State
		No Current DTC	

S/W Ver.	M-E-K-01-00-0238	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0179	OS Ver.	Android 10