



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Seah Min Fann BLK 1 LORONG LEW LIAN #05-14 SINGAPORE 531001 Contact No Mobile: 97809301	Cust No/Name /Seah Min Fann Reg No/Reg Date SKZ6596R / 29/01/201 Date In/Mileage / 0 Chassis No KNAFZ411MF5537893 Engine No G4FGFH600855 Make/Model KIA/FORTE K3 1.6 A SX ADQ Colour/Trim SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	28/01/2021/ 14:23		442 / CocoLu	27921

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, FRT FENDER LH, 400x2				1220.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				100.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH 350x2				1100.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY TRANSFER FRT LEFT RIM				30.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				200.00
A 90000001 RENEW FRT UNDERCARRIAGE				350.00
M SUNDRY Sundry	1.00	728.00	00.00	728.00
M COVER-FR BUMPER / DR	1.00	13.00	00.00	13.00
M BRACKET-FR BUMPER SIDE MTG, LH / DR	1.00	435.00	00.00	435.00
M PANEL-FENDER, LH / DR	1.00	109.00	00.00	109.00
M GUARD ASSY-FRONT WHEEL, LH / CUT	1.00	1870.00	00.00	1870.00
M LAMP ASSY-HEAD, LH / CUT	1.00	150.00	00.00	150.00
M HUB ASSY-FR WHEEL / X MIN	1.00	958.00	00.00	958.00
M WHEEL ASSY-ALUMINIUM / CUT	1.00			

Estimate

Steve (LKK)
28/1/21, 3-30pm

P/P

By Belmy

5 days

OD - N/A AL

Express - ?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Confirm & accepted by

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

Nett

7473.00

7% GST on

Total Payable

7,473.00

523.11

7,996.11

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.